## NSN 2835-01-073-8051

Repairability:

Turbine Engine Axial-centrifugal Compressor Rotor - Page 1 of 1



iew Online at https://aerobasegroup.kr/nsn/2835-01-073-8051	
helf Life:	
l/a	
nit Of Measure:	
ea	
emilitarization:	
es - demil/mli	
iig:	
23900	
lazmat:	
lo	

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.