View NSN Online: https://aerobasegroup.kr/nsn/5910-00-146-4793 ELECTRICAL UTILITIES CO -- 1A9Z10301 -- 5910-00-146-4793 Product ID:1A9Z10301 MSDS Date:01/01/1985 FSC:5910 NIIN:00-146-4793 MSDS Number: BDCJR === Responsible Party === Company Name: ELECTRICAL UTILITIES CO Address:1 INDUSTRIAL DR Box:97 City:SNOW HILL State:NC ZIP:28580-0453 Country:US **Emergency Phone Num:NONE** CAGE:01102 === Contractor Identification === Company Name: CAPTRON INC Address:1 INDUSTRIAL DR Box:97 City: SNOW HILL State:NC ZIP:28580-0453 Country:US Phone:919-747-5943 CAGE:81133 Company Name: ELECTRICAL UTILITIES CO. Box:97 CAGE:01102 ======= Composition/Information on Ingredients ======== Ingred Name: POLYCHLORINATED BIPHENYLS (PCBS) (SARA III) CAS:1336-36-3 RTECS #:TQ1350000 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Effects of Overexposure: ABSORBED THRU SKIN, LUNGS, I

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.
======== Accidental Release Measures =========
Spill Release Procedures:USE ABSOR BENT & DIKES TO PREVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.
========== Handling and Storage ============
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT SKI N CONTACT Supplemental Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.
======================================
HCC:V1 Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR
========= Stability and Reactivity Data =========
STRONG OXIDIZERS
======== Disposal Considerations ===========
Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TE

NTESTINE.CAUSES

MPERATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED..

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibil ity for the suitability of this information to their particular situation.