

KESTER SOLDER -- #197 ROSIN FLUX -- 3439-00-162-8388

=====
Product Identification
=====

Product ID:#197 ROSIN FLUX

MSDS Date:01/01/1987

FSC:3439

NIIN:00-162-8388

MSDS Number: BDDQK

=== Responsible Party ===

Company Name:KESTER SOLDER

Address:515 E TOUHY

City:DES PLAINES

State:IL

ZIP:60018-2675

Country:US

Info Phone Num:312-699-5594

Emergency Phone Num:312-699-5594

CAGE:GO345

=== Contractor Identi

fication ===

Company Name:KESTER SOLDER

Address:515 EAST TOUHY AVENUE

City:DES PLAINES

State:IL

ZIP:60018-2675

Country:US

Phone:708-297-1600

CAGE:GO345

Company Name:KESTER SOLDER DIVISION OF LITTON SYSTEMS, INC.

Address:515 E. TOUHY AVENUE

Box:City:DES PLAINES

State:IL

ZIP:60018

Country:US

Phone:847-297-1600

CAGE:75297

=====
Composition/Information on Ingredients
=====

Ingred Name:ROSIN, CAS#8050-09-7 SEE SUPP DATA

Fraction by Wt: 37.0%

Ingred Name:ISOPROPYL ALCOHOL (SARA I

II)
CAS:67-63-0
RTECS #:NT8050000
Fraction by Wt: 56.0%
OSHA PEL:400 PPM/500 STEL
ACGIH TLV:400 PPM/500STEL;9192

===== Hazards Identification =====

Effects of Overexposure:CONTACT MAY CAUSE SKIN AND EYE IRRITATION;ROSIN
MAY CAUSE RASH,HEADACHE OR RESP IRRIT OR NARCOSIS.

===== First Aid Measures =====

First Aid:INHALE:REMOVE TO FRESH AIR, GIVE CPR/O*2 IF
NEED;EYES/SKIN:FLUSH W LG AMTS H*20 FOR 15 MIN;INGEST:RINSE
MOUTH;
GET MEDICAL ATTENTION FOR EYES, BREATHING DIFFICULTY, OR OTHER
SYMPTOMS OF OVEREXPOSURE.

===== Fire Fighting Measures =====

Flash Point:65F/18.3C (T.O.C
Autoignition Temp:Autoignition Temp Text:750F
Lower Limits:2.0
Upper Limits:12.0
Extinguishing Media:CO*2,FOAM,DRY CHEMICAL
Fire Fighting Procedures:USE WATER SPRAY TO COOL CONTAINERS AND CONTROL
VAPORS.
Unusual Fire/Explosion Hazard:USE CARE.AUTO IGNITION TEMPERATURE IS
750F.

===== Accidental Release Measures =====

Spill Release Procedures:USE PROPER PERSONAL PROTECTION;USE SUITABLE
ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL.

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL,DRY AND WELL VENTILATED
AREA.KEEP AWAY FROM HEAT,OPEN FLAME AND SPARKS.KEEP CONTAINER
CLOSED WHEN NOT IN USE.
Other Precautions:AVOID CONTACT WITH SKIN,EYES AND CLOTHES;DO NOT
BREATHE VA

PORS;WASH THOROUGHLY AFTER EACH USE.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR FOR ORG
VAPORS/MIST IF ABOVE TLV.

Ventilation:PROVIDE MECHAN(GEN/LOCAL EXHAUST)VENT TO MAINTN