View NSN Online: https://aerobasegroup.com/nsn/9150-00-189-6729 WOLF'S HEAD OIL REFINING CORP. -- WOLF'S HEAD SPECIAL DUTY SERIES 3 OIL, GR 30 --9150-00-189-6729 ============= Product Identification ================= Product ID:WOLF'S HEAD SPECIAL DUTY SERIES 3 OIL,GR 30 MSDS Date:01/01/1985 FSC:9150 NIIN:00-189-6729 MSDS Number: BDHRT === Responsible Party === Company Name: WOLF'S HEAD OIL REFINING CORP. Emergency Phone Num: (814) 677-6190 CAGE:DO762 === Contractor Identification Company Name: PENNZOIL CO Address:700 MILIAM PENNZOIL PL Box:2967 City:HOUSTON State:TX ZIP:77252-2967 Country:US Phone:800-546-6227 CAGE:01326 Company Name: WOLF'S HEAD OIL COMPANY Address:P.O.BOX 808

Box:808 City:OIL CITY State:PA

ZIP:16301-0808 Phone:713-236-6070

CAGE:DO762

======= Composition/Information on Ingredients ========

Ingred Name:PETROLEUM HYDROCARBON (TLV OF 5 MG/CUM OIL MIST)

========= Hazards Identification ===============

Effects of Overe

ASPIR PNEUM FROM MIST. INGEST: POSS NAVSEA,LAXATIVE EFF
======================================
First Aid:EYES: FLUSH W/ CLEAN,WARM WATER. IF LIQ IS HOT TREAT FOR BURNS,CALL MD. SKIN: WIPE OFF EXCESS. WASH W/ SOAP/WATER. IF LIQ HOT, CHILL AREA, TREAT FOR SHOCK, CALL MD. INH: REMOVE TO FRESH AIR. IF NEC.GI VE ARTIF RESP,CALL MD. INGEST: DO NOT INDUCE VOMIT
======================================
Flash Point:440F COC Extinguishing Media:FOAM, DRY CHEMICAL, CO*2 Fire Fighting Procedures:DO NOT USE WATER AS A SOLID STREAM - POSS FROTH,SPREAD FIRE Unusual Fire/Explosion Hazard:NONE
========= Accidental Release Measures ============
Spill Release Procedures:SM SPILLS: PICK UP W/ABSORBENTS (PAPER, CLOTH,DRY SAND, EARTH). LG SPILLS: USE PUMPS, BUCKETS,SHOVELS OR OTHER APPLICABLE TOOLS. PUT DRY SAND OR SPECIAL OIL ABSORBENTS ON OIL
Y AREAS TO HELP PREVENT AC CIDENTS.
======================================
Handling and Storage Precautions:FOR STORAGE & HADLING REQUIREMENTS, SEE: 49 CFR 1910.106 - FLAM & COMBUST LIQUIDS NFPA NO. 30 - FLAM & COMBUSTIBLE LIQUIDS CODE. Other Precautions:DO NOT TRANSFER RO UNMARKED CONTAINERS. FOLLOW DOT
REGULATIONS DURING TRANSPORT. SHOULD A SITUATION ARISE REQUIRING ADDITIONAL PROPRIETARY INGRED INFORMATION CONTACT WOLF'S HEAD.
======= Exp osure Controls/Personal Protection ==========
Respiratory Protection:NIOSH/MSHA APPRVD RESP PROT FOR PARTICULAR EXPOS OF CONCERN Ventilation:VENTIL IAW GOOD ENGINEERING PRACTICE TO KEEP BELOW TLV LIMIT
Protective Gloves:INSULATED TYPE Eye Protection:SAFETY GOG OR FACE SHIELD Other Protective Equipment:PROT EXPOS AREAS W/PLASTIC OR RUBBERIZED PERSONAL PROT EQUIP Supplemental Safety and Health CONTAINER SIZE: 55 GAL.
======================================

xposure:SKIN: PRLNG EXPOS POSS DERMATITIS. INH: POSS

=====

HCC:V6

Boiling Pt:B.P. Text:>900F

Spec Gravity:0.893

Solubility in Water: NEGLIGIBLE

Appearance and Odor: OPAQUE - DARK - MILD ODOR

======== Stability and Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES

OXIDIZERS

Stability Condition to Avoid: NONE

Hazardous Decomposition Products:CARBON MONOXIDE & SOOT CAN BE PROD IN AN O*2 DEFICIENT FIRE.

======= Disposal Considerations ===========

Waste Disposal Methods:DISPOSAL MUST B
E IAW ALL APPLICABLE LOCAL, STATE
& FED LAWS. QUANTITIES MAY BE DISPOSED OF CONTROLLED INCINERATION
OR IN A SANITARY LANDFILL ACCD TO MFR.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.