View NSN Online: https://aerobasegroup.kr/nsn/3040-00-361-6450

SQUARE D CO. -- 5100-071-62 -- 6110-00-361-6450

Product ID:5100-071-62 MSDS Date:01/01/1985

FSC:6110

NIIN:00-361-6450

MSDS Number: BDXFF
=== Responsible Party ===
Company Name: SQUARE D CO.
Address: SUMTER HWY 76 AND 378

City:COLUMBIA

State:SC

ZIP:29209-1639 Country:US CAGE:LO295

=== Contractor Identification ===

Company Name: SQUARE CO COLUMBIA MFG PLANT

Address:SU

MTER HWY 76 AND 378

Box:City:COLUMBIA

State:SC

ZIP:29209-1639

Country:US CAGE:51920

Company Name: SQUARE D CO. Address: SUMTER HWY 76 AND 378

Box:City:COLUMBIA

State:SC

ZIP:29209-1639 Country:US CAGE:LO295

======= Composition/Information on Ingredients ========

Ingred Name: ASBESTOS (AMIANTHUS, OBSOLETE AMOSITE), (FOR OSHA PEL, SEE 29CFR 1910.1101)

CAS:1332-21-4

RTECS #:CI6475000

OSHA PEL:0.2 FIBERS/CC

ACGIH TLV:0.5 FIBERS/CC; A1;89

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

\_\_\_\_\_

====== Hazards Identification ===========
Effects of Overexposure:ASBESTOS DUST IS KNOWN HUMAN CARCINOGEN.ALSO COUGH,SHORT OF BREATH,WEAKNESS,CYANOSIS,ETC.
======================================
First Aid:SKIN:CONSULT DOCTOR FOR DERMATITIS.EYES:FLUSH WITH WATER FOLLOWED BY TREATMENTS OF OPTHALMOLOGIST.INHALATION:CONSULT PHYSICIAN AT ONCE.
======================================
Extinguishing Media:EXTINQUI SH W. AGENT SUITABLE FOR SURROUNDING FIRE. Fire Fighting Procedures:WEAR SELF-CNTND BRTHG APP
========= Accidental Release Measures ==========
Spill Release Procedures:PICK UP MATERIAL & RETURN TO CONTAINER.IF ANY BROKEN MATERIAL EXISTS,BE CAREFUL TO AVOID DUSTING CONDITIONS.PLACE BROKEN MATERIAL INTO A SEALED CONTAINER.VACUUM OR WET CLEAN ONLY.DO NOT DRY SWEEEP.
========== Handling and Storage ===========
Handling and Storage Precaution s:AVOID CUTTING OR GRINDING ON ITEM.AVOID ANY DUSTING CONDITIONS.MAINTAIN GOOD HOUSEKEEPING.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:NIOSH APPROVED DUST MASK AS A MINIMUM.SELF CONT APP FOR DUSTING COND Ventilation:PROVIDE GOOD LOCAL VENTILATION TO KEEP BELOW PEL. Protective Gloves:WORKING GLOVES Eye Protection:SAFETY GLASSES Other Protective Equipment:FULL WORK CLOTHING TO PREVENT REPEATED OR
PROLONGED CONTACT. Supplemental Safety

ASBESTOS IS BOUND UP & NOT LOOSE.
======== Physical/Chemical Properties =========
HCC:T6 Appearance and Odor:ASBESTOS FIBERS IN BOUND FORM IN FRICTION LINING.
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES NONE KNOWN Hazardous Decomposition Products:NONE KNOWN

SAFETY DATA DEVELOPED BY DGSC-STF.STORAGE CODE BASED ON FACT THAT

Waste Disposal Methods:PLACE IN SEALED PLASTIC BAG CONTAINER.ULTIMATE DISPOSAL MUST COMPLY WITH ALL LOCAL, STATE & FEDERAL REGULATIONS.

======= Disposal Considerations ===========

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.

and Health