

GENERAL ELECTRIC CO. SWITCHGEAR CONT. DIV. -- 21F418 -- 5910-00-644-3506

=====
Product Identification
=====

Product ID:21F418

MSDS Date:01/01/1985

FSC:5910

NIIN:00-644-3506

MSDS Number: BFJVQ

=== Responsible Party ===

Company Name:GENERAL ELECTRIC CO. SWITCHGEAR CONT. DIV.

Address:3135 EASTON TURNPIKE

City:FAIRFIELD

State:CT

ZIP:06431

Country:US

Emergency Phone Num:NONE

CAGE:71669

=== Contractor I

dentification ===

Company Name:GENERAL ELECTRIC CO SWITCHGEAR & CONTR

Address:3135 EASTON TURNPIKE

Box:City:FAIRFIELD

State:CT

ZIP:06431

Country:US

Phone:203-373-2211

CAGE:71669

=====
Composition/Information on Ingredients
=====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)

CAS:1336-36-3

RTECS #:TQ1350000

EPA Rpt Qty:1 LB

DOT Rpt Qty:1 LB

=====
Hazards Identification
=====

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTIN

E.CAUSES

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

=====
First Aid Measures
=====

First Aid:EYES:FLUSH W/WATER IMMED.SKIN:WASH W/SOAP IMMED.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR. AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING BUT DO NOT MAKE UNCONSCIOUS PE RSON VOMIT.

=====
Accidental Release Measures
=====

Spill Release Procedures:USE ABSORBENT & DIKES TO PR EVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD
Ventilation:LOCAL EXHAUST
Protective Gloves:RUBBER-IMPERV
Eye Protection:GOGGLES FACE SHIELD
Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT
Suppleme
ntal Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS.CAUSES STILLBIRTHS.IRRITATES EYES,NOSE,THROAT.

=====
Physical/Chemical Properties
=====

HCC:V1
Appearance and Odor:LIGHT STRAW COLORED LIQUID,AROMATIC ODOR.

=====
Stability and Reactivity Data
=====

STRONG OXIDIZERS.

=====
Disposal Considerations
=====

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINE

RATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.