View NSN Online: https://aerobasegroup.com/nsn/6850-00-967-1152 EXXON COMPANY, U.S.A. -- VARSOL 18 -- 6850-00-967-1152 ============= Product Identification ======================== Product ID: VARSOL 18 MSDS Date:01/01/1987 FSC:6850 NIIN:00-967-1152 MSDS Number: BFZYV === Responsible Party === Company Name: EXXON COMPANY, U.S.A. Address:800 BELL ST Box:2180 City:HOUSTON State:TX ZIP:77252-2180 Country:US Emergency Phone Num:713-870-6000 CAGE:EO384 === Contractor Identification === Company Name: EXXON COMPANY U.S.A. Box:2180 City:HOUSTON State:TX ZIP:77252-2180 Country:US Phone:713-656-5949 / 713-656-3424 CAGE:29700 Company Name: EXXON COMPANY, U.S.A. Address:800 BELL ST Box:2180 City:HOUSTON State:TX ZIP:77252-2180 Country:US Phone:713-870-6000 CAGE:EO384 ======= Composition/Information on Ingredients ======== Ingred Name:PETROLEUM HYDROCARBONS Fraction by Wt: 100%

ACGIH TLV:200 PPM (MFR)

========== Hazards Identification ==============

Effects o

REPEATED SKIN CONTACT WILL DRY OR DEFAT SKIN
======================================
First Aid:INHALATION-MOVE TO FRESH AIR.CALL DOCTOR.GIVE OXYGEN IF BREATHING IRREGULAR.INGESTION-DO NOT INDUCE VOMIT.CALL DOCTOR.SKIN-REMOVE SOILED CLOTHES.WASH WITH SOAP & WARM WATER EYES-FLUSH WITH WATER FOR 1 5 MIN OR UNTIL IRRITATION SUBSIDES.
======================================
Flash Point:106F/41C Lower Limits:0.9 Upper Limits:6.0 Extinguishing Media:FOAM,DRY CHEMICAL,CARBON DIOXIDE,WATER FOG OR SPRAY Fire Fighting Procedures:USE AIR SUPP EQUIP IN CLOSE AREAS.COOL EXPOSED CONT W/WATER Unusual Fire/Explosion Hazard:DO NOT MIX-STORE W/STRONG OXIDIZERS LIKE
LIQUID CHLÖRINE OR CONC VAPORS.(COMBUSTIBLE LIQUID) ===================================
Spill Release Procedures:REMOVE IGNITION SOURCES.KEEP PEOPLE AWAY.RECO
VER FREE LIQUID.ABSORB WITH SAND,EARTH SAWDUST ETC.AVOID BREATHING VAPORS.VENTILATE AREA.OPEN WINDOWS.KEEP OUT OF SEWERS,WATERCOVERS ETC. OR EXTENSIVE LAND AREAS.
========== Handling and Storage ============
Handling and Storage Precautions:KEEP CONTAINERS CLOSED WHEN NOT IN USE. DO NO HANDLE OR STORE NEAR HEAT,SPARKS,FLAME OR OXIDIZERS.PROVIDE VENTILATION EQUAL TO OUTDOORS. Other Precautions:AVOID BREATHING VAPORS.AVOID PROLONGED OR REPEATED SKIN CO NTACT.REMOVE CONTAMINATED CLOTHING,LAUNDER BEFORE REUSE DRY SOILED SHOES BEFORE REUSE.WASH SKIN THOROUGHLY WITH SOAP & WATER.
====== Exposure Controls/Personal Protection =======
Respiratory Protection:HYDROCARBON VAPOR CANNISTER OR SUPPLIED-AIR RESPIRATOR Ventilation:LOCAL-FACE VELOCITY>60 FPM.USE EXPLOSION PROOF FANS Protective Gloves:CHEM RESISTANT Eye Protection:SPLASH GOGGLES OR SHIELD Other Protective Equipment:CHEMICAL RESISTANT APRON OR OTHER CLOTHING. Supplement

f. Over exposure: DIZZINESS, HEADACHE, UNCONSCIOUSNESS. PROLONGED. OR.

al Safety and Health UPDATE PER NON-OSHA MSDS DTD 10 AUGUST 79.

========= Physical/Chemical Properties ==========

HCC:F4

Boiling Pt:B.P. Text:313F/156C

Vapor Pres:1.0 Vapor Density:5.0 Spec Gravity:0.78

Evaporation Rate & Evaporation R