View NSN Online: https://aerobasegroup.kr/nsn/5955-01-021-0758 RAYTHEON CO. FOUNDRY AVE. WALTHAM MA. 02254 -- QKA-1432 -- 5865-01-021-0758 Product ID:QKA-1432 MSDS Date:01/01/1985 FSC:5865 NIIN:01-021-0758 MSDS Number: BGDZV === Responsible Party === Company Name: RAYTHEON CO. FOUNDRY AVE. WALTHAM MA. 02254 Emergency Phone Num:419/862-2745X148 CAGE:MO579 === Contractor Identification === Company Name: RAYTHEON CO, EXECUTIVE OFF Address:141 SPRING ST Box:City:LEXINGTON State:MA ZIP:02173-7801 Country:US Phone:617-862-6600 CAGE:49956 Company Name: RAYTHEON CO. FOUNDRY AVE. WALTHAM MA. 02254 CAGE:MO579 ======= Composition/Information on Ingredients ======== Ingred Name:BERYLLIUM OXIDE (AS BERYLLIUM) CAS:1304-56-9 RTECS #:DS4025000 OSHA PEL:0.002 MG/M3; C,0.005 ACGIH TLV:0.002 MG/M3; A2;8990 ========= Hazards Identification =============== Effects of Overexposure: ACUTE: PNEUMONITIS. ACUTE LOCAL: IRRITANT

CHRONIC: BERYLLIOSIS. POSSIBLE CARCINOGEN.

First Aid:ALL B O IMPLANTED IN SKIN MUST BE REMOVED IMEDIATELY. WASH THOROUGHLY WITH WATER. UPON INHALATION OBTAIN X-RAY.

========= Accidental Release Measures ============

Spill Release Procedures: CONTAIN. HIGHLY TOXIC BY INHALATION.
RESPIRATORY PROTECTION REQUIRED IF MATERIAL BECOMES AIRBORNE.
CLEAN UP WITH WET M

O TO BECOME AIRBORNE. ITEM IS HAZARD ONLY IF TUBE IS BROKEN AND SPRE
=========== Handling and Storage ============
Handling and Storage Precautions:USE GLOVES AND PROTECTIVE CLOTHING. DO NOT TAKE CONTAMINATED ITEMS HOME. KEEP CONTAINERS TIGHTLY CLOSED.  Other Precautions:MATERIAL IS HAZARDOUS ONLY IF TUBE BROKEN AND B O
IS SPREAD.  ====== Exposure Controls/Personal Protection ====================================
· ===
Respiratory Protection:ONLY IF MATERIAL BECOMES AIRBORNE. Ventilation:YES Protective Gloves:YES Eye Protection:FACESHIELD Supplemental Safety and Health BRUSH WELLMAN, ELMORE OHIO SUPPLIES RAYTHEON WITH B O TO MFG TUBE.
========= Physical/Chemical Properties ==========
HCC:M1 Boiling Pt:B.P. Text:3960 C. Spec Gravity:3.016 Appearance and Odor:WHITE POWDER.
========= Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES St
ability Condition to Avoid:SKIN CONTACT OR INHALATION.
======= Disposal Considerations ==========
Waste Disposal Methods: IN ACCORDANCE WITH ALL LOCAL, STATE AND FEDERAL REGULATIONS.

OP OR WET RAGS. DO NOT DRY SWEEP OR CAUSE B

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclai

ms all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.