View NSN Online: https://aerobasegroup.kr/nsn/3439-01-012-1756

EUTECTIC CORPORATION -- XUPER 185 XFC -- 3439-01-012-1756

Product ID:XUPER 185 XFC MSDS Date:03/15/1993

FSC:3439

NIIN:01-012-1756

MSDS Number: BHBCB === Responsible Party ===

Company Name: EUTECTIC CORPORATION

Address:40-40 172ND STREET

City:FLUSHING

State:NY

ZIP:11358-2799 Country:US

Info Phone Num:718-358-4000

Emergency Phone Num:718-358-4000

CAGE:EO060 === Cont

ractor Identification ===

Company Name: EUTECTIC CORP

Address:9625-J SOUTHERN PINE BLVD

Box:City:CHARLOTTE

State:NC ZIP:28273 Country:US

Phone:704-527-9800/800-221-1433

CAGE:72271

Company Name: EUTECTIC CORPORATION

CAGE:EO060

======= Composition/Information on Ingredients ========

Ingred Name: COPPER (DUST & MIST), BRONZE POWDER

CAS:7440-50-8

RTECS #:GL5325000 Fraction by Wt: 40-50%

Other REC Limits:1 MG(CU)/M3 (DUST)
OSHA PEL:0.1 MG(CU)/M3 (FUME)
ACGIH TLV:0.2 MG/M3 (FUME)

EPA Rpt

Qty:5000 LBS

DOT Rpt Qty:5000 LBS

Ingred Name:ZINC CAS:7440-66-6

RTECS #:ZG8600000 Fraction by Wt: 30-40% ACGIH TLV:10 MG/CUM EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:NICKEL (SOLUBLE) (SUSPECTED HUMAN CARCINOGEN BY NTP, IARC,

ACGIH) INTENDED CHANGE (IC)

CAS:7440-02-0

RTECS #:QR5950000 Fraction by Wt: 10-15%

Other REC Limits: 1 MG/CUM

OSHA PEL:1 MG/CUM

ACGIH TLV:0.05 MG/CUM IC

Ingred Name: BORIC ACID, ORTHOBORIC ACID

CAS:10043-35-3 RTECS #:ED4550000

Ingred Name: SODIUM TETRABORA

TE DECAHYDRATE, SODIUM BORATE, BORAX,

ANHYDROUS BORAX

CAS:1303-96-4 RTECS #:VZ2275000

ACGIH TLV:5 MG/CUM

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO

Health Hazards Acute and Chronic: INHALATION: NOSE & THROAT IRRITATION,

DIZZINESS, NAUSEA, DRYNESS, LUNG & OTHER ORGAN DAMAGE, METAL FUME

FEVER. EYES/SKIN: INJURY & BURNS, POSSIBLE CHEMICAL BURNS.

INGESTION: HARMFUL.

Explanation of Carcinogenicity: SEE INGREDIENTS

Effects of Overexposure: INHALATION: BRONCHIAL ASTHMA, LUNG FIBROSIS,

PNEUMOCONIOSIS (IRON DEPOSITS IN LUNG).

First Aid:INHALATION: REMOVE TO FRESH AIR. SKIN: WASH W/SOAP & WATER TO REMOVE ALL RESIDUE. EYES: FLUSH THOROUGHLY W/WATER FOR AT LEAST 15 MINS TO REMOVE ALL RESIDUE. INGESTION: CALL PHYSICIAN OR POISON CONTROL CENTER. OBTAIN MEDICAL

ATTENTION IN ALL CASES.
======================================
Flash Point:NONFLAMMABLE Extinguishing Media:CO2, DRY CHEMICAL FOAM TYPE Fire Fighting Procedures:WEAR APPROVED SELF-CONTAINED BREATHING APPARATUS. Unusual Fire/Explosion Hazard:WELDING ARC & SPARKS & BRAZING FLAMES CAN IGNITE COMBUSTIBLES & FLAMMABLES. CANS UNDER PRESSURE & FLAMMABLES MAY EXPLODE.
======================================
Handling and Storage Pr ecautions:FUMES, GASES & DUST GIVEN OFF DURING HEATING, WELDING, BRAZING, SOLDERING, CUTTING OR THERMAL SPRAY PROCESSES CANNOT BE CLASSIFIED SIMPLY. Other Precautions:ELECTRICAL SHOCK CAN KILL. TRAIN WELDER TO KEEP HIS/HER FACE AWAY FROM THE FUME/DUST PLUME. TRAIN WORKERS NOT TO TOUCH LIVE ELECTRICAL PARTS & TO INSULATE THEMSELVES FROM WORK & ELECTRICAL GROUND.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:USE NIOSH APPROVED RESP IRATOR
Ventilation:USE ENOUGH GENERAL & LOCAL EXHAUST AT WORK SITE TO KEEP ALL FUMES & DUST FROM WORKER'S BREATHING ZONE Protective Gloves:WELDER'S Eye Protection:HELMET OR FACE SHIELD W/FILTER LENS
Other Protective Equipment:ARM PROTECTORS, APRONS, HATS, SHOULDER PROTECTION. PROVIDE PROTECTIVE SCREENS/FLASH GOGGLES.
Supplemental Safety and Health COMPOSITON & QUANTITY OF FUMES/GASES ARE DEPENDENT UPON METAL BEING WELDED/PROCESS/PROCEDURES/ELECTRODES OR OTHER CONSUMABLES USED. OT
HER INFLUENCES: COATINGS ON WORKPIECE, NUMBER OF WORKERS & VOLUME OF WORK SPACE, QUALITY/AMOUNT OF VENTILATION, POSITION OF WELDERS HEAD TO FUME PLUME & CONTAMINANTS IN ATMOSPHERE.
========= Stability and Reactivity Data ===========
Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid:SPARKS & FLAMES Hazardous Decomposition Products:FLUORIDE COMPOUNDS, METAL OXIDES, CO, CO2, SILICA, OZONE, NITROGEN OXIDES, & INERT GASES
======== Dis

posal Considerations =========

Waste Disposal Methods:DISPOSE OF WASTE MATERIAL, POWDERS, GRINDING OR FILTER IN ENVIRONMENTALLY SENSITIVE MANNER IN ACCORDANCE W/FEDERAL, STATE, & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and d

isclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.