View NSN Online: https://aerobasegroup.com/nsn/3439-00-009-8808

## GARDINER METAL CO -- GF 1100 SERIES FLUXES (GF-1125,GF-1135,1145 -- 3439-00-009-8808

======== Product Identification ============

Product ID:GF 1100 SERIES FLUXES (GF-1125,GF-1135,1145

MSDS Date:05/01/1990

FSC:3439

NIIN:00-009-8808

MSDS Number: BHPFN === Responsible Party ===

Company Name: GARDINER METAL CO Address: 4820 SOUTH CAMPBELL AVENUE

City:CHICAGO

State:IL ZIP:60632 Country:US

Info Phone Num:312-847-

0100

Emergency Phone Num:312-847-0100, 800-424-9300

CAGE:73766

=== Contractor Identification ===

Company Name: GARDINER METAL CO Address: 4820 SOUTH CAMPBELL AVENUE

City:CHICAGO

State:IL ZIP:60632 Country:US

Phone:312-847-0100, 800-424-9300

CAGE:73766

Company Name: GARDINER SOLDER CO, DIV OF GARDINER METAL CO

Address: 4820 S CAMPBELL AVE

Box:City:CHICAGO

State:IL

ZIP:60632-1416

Country:US

Phone:312-847-0100/800-424-9300(CHEMTREC)

CAGE:56244

===== Composition/Information on Ingredients ===

========

Ingred Name: ISOPROPYL ALCOHOL (SARA III)

CAS:67-63-0

RTECS #:NT8050000 Fraction by Wt: 65-75%

Other REC Limits:NONE SPECIFIED OSHA PEL:400 PPM/500 STEL

ACGIH TLV:400 PPM/500STEL;9192

Ingred Name:ROSIN ACID

CAS:8050-09-7 Fraction by Wt: 25%

Other REC Limits: NONE SPECIFIED

========== Hazards Identification ==============

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:

**ACUTE:IRRITATION OF** 

EYES,SKIN,RESPIRATORY OR G.I.TRACTS;CNS EFFECTS LIKE HEADACHE,DIZZINESS,NAUSEA,VOMITING AND POSSIBLE UNCONSCIOUSNESS;REDNESS OR BURNS OF EYES/SKIN

POSSIBLE.CHRONIC:TISSUE DAMAGE PO SSIBLE

Explanation of Carcinogenicity: DATA PER MSDS

Effects of Overexposure: SEE HEALTH HAZARDS DATA.

Medical Cond Aggravated by Exposure:PERSONS WITH A HISTORY OF AILMENTS OR WITH A PRE-EXISTING DISEASE INVOLVING THE EYES, SKIN, OR RESPIRATORY TRACT MAY BE AT INCREASED RISK FROM EXPOSURE.

First Aid:INHALATION:REMOVE TO FRESH AIR. RESUSCITATE IF NOT BREATHING. GET MEDICAL ATTENTION. EYES:IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR 15 MINUTES HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. SKIN:REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP AND WATER. IF IRRITATION PERSISTS, GET MEDICAL ADVICE. INGESTION:DO NOT INDUCE VOMITING. GIVE NOTHING BY MOUTH IF UNCONSCIOUS. GET IMMEDIATE

MEDICAL ATTENTION.
======================================
Flash Point Method:TOC Flash Point:52.0F,11.1C Lower Limits:2.0 Upper Limits:12.0
Extinguishing Media:USE CARBON DIOXIDE, FOAM, DRY CHEMICAL, OR WATER FOG.
Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard:FLAMMABLE MATERIAL,WATER MAY SPREAD
FLAMES.FIRE OR EXCESSIVE HEAT MAY CAUSE PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS.
========= Accidental Release Measures ==========
Spill Release Procedures:USE PROPER PERSONAL PROTECTION;REMOVE ALL IGNITION SOURCES;CONTAIN FREE MATERIAL IF POSSIBLE;USE SUITABLE INERT ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL IN AN APPROVED CONTAINER.  Neutralizing Agent:NOT APPLICABLE.
======================================
Handling and Storage Precautions:STORE IN A COOL, DRY, WELL VENTILATED AREA. KEEP CONTAINERS TIGHTLY CLOSED WHEN NOT IN USE.DO NOT SMOKE IN WORK AREA.
Other Precautions:DO NOT BREATHE MIST. AVOID PROLONGED OR REPEATED BREATHING OF VAPOR. AVOID CONTACT WITH EYES. USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING.
====== Exposure Controls/Personal Protection ========
Respiratory Protection: USE NIOSH/MSHA APPROVED RESPIRATOR FOR ORGANIC

VAPOR

S/MIST AS REQUIRED IF ABOVE PEL/TLV. Ventilation:LOCAL/GENERAL TO MAINTAIN PEL/TLV. Protective Gloves: NEOPRENE, NITRILE, OR NATURAL RUBBER Eye Protection: SAFETY GOGGLES WITH OPTIONAL FACE SHIELD Other Protective Equipment: EYE WASH STATION AND SAFETY SHOWER, WORK CLOTHING AND APRON AS REQUIRED. Work Hygienic Practices: OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR FOOTWEAR. Supplemental Safety and Health AVOID PROLONGED OR REPE ATED EXPOSURE. DO NOT GET ON SKIN OR IN EYES. DO NOT BREATHE VAPORS OR MISTS. ======== Physical/Chemical Properties ============ HCC:F2 Boiling Pt:B.P. Text:181F,83C Vapor Pres:33 Vapor Density:2.7 Spec Gravity:0.85-0.89 Evaporation Rate & Reference: 1.7(N-BUTYL ACETATE = 1) Solubility in Water: APPRECIABLE Appearance and Odor: AMBER LIQUID, ALCOHOL ODOR ======== Stability and Reactivity Data ========== Stability Indicator/Materials to Avoid:YES **STRONG OXIDIZING AGENTS** Stability Condition to Avoid: HIGH TEMPERATURES, SPARKS, AND OPEN FLAMES Hazardous Decomposition Products: CARBON MONOXIDE, CARBON DIOXIDE AND OTHER UNIDENTIFIED COMPONENTS.

======= Disposal Considerations ============

Waste Disposal Methods: CONSULT LOCAL AUTHORITIES. DISPOSAL MUST BE MADE IN ACCORDANCE WITH ALL APPLICABLE FEDERAL, STATE AND LOCAL LAWS AND REGULATIONS.NO SMOKING IN WORK AREA.

Disclaimer (provided with this information by the

## compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.