

CHEMRAY COATINGS -- PAINT, EXTERIOR, DULL BLACK 51518 -- 8010-00-286-7854  
===== Product Identification =====

Product ID:PAINT, EXTERIOR, DULL BLACK 51518

MSDS Date:01/01/1987

FSC:8010

NIIN:00-286-7854

MSDS Number: BHRGP

=== Responsible Party ===

Company Name:CHEMRAY COATINGS

Address:209 N. MICHIGAN AVENUE

City:KENILWORTH

State:NJ

ZIP:07033

Country:US

Info Phone Num:201-245-1111/800-924-7854 CHEMTR

AC

Emergency Phone Num:201-245-1111/800-924-7854 CHEMTRAC

Preparer's Name:FRED ARMSTRONG

CAGE:OBRN9

=== Contractor Identification ===

Company Name:CHEMRAY COATING CORP

Address:209 N MICHIGAN AVE

Box:City:KENILWORTH

State:NJ

ZIP:07033

Country:US

Phone:201-245-1111

CAGE:33832

Company Name:CHEMRAY COATINGS CORP.

Address:209 N. MICHIGAN AVE.

Box:NA

City:KENILWORTH

State:NJ

ZIP:07033

Country:US

Phone:800-924-9300

CAGE:OBRN9

===== Composition/Information on Ingredients =====

Ingred

Name:STODDARD SOLVENT  
CAS:8052-41-3  
RTECS #:WJ8925000  
Fraction by Wt: 40%  
OSHA PEL:500 PPM  
ACGIH TLV:100 PPM; 9293

Ingred Name:LEAD DRIER  
Fraction by Wt: 0.25%  
OSHA PEL:.05 MG/M3  
ACGIH TLV:.15 MG/M3

Ingred Name:COBALT DRIER  
Fraction by Wt: 0.15%  
OSHA PEL:.3 MG/M3  
ACGIH TLV:.1 MG/M3

=====  
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:  
NAUSEA, HEADACHES, DIZZINESS CAUSED BY  
OVER INHALATION.  
Effects of Overexposure:NAUSEA, HEADACHES, DIZZINESS CAUSED BY OVER  
INHALATION.

=====  
===== First Aid Measures =====

First Aid:EYE CONTACT: FLUSH WITH WATER 15 MINUTES OR UNTIL IRRITATION  
SUBSIDES. IF IRRITATION PERSISTS, CALL PHYSICIAN. SKIN CONTACT:  
REMOVE CONTAMINATED CLOTHING & WASH THOROUGHLY WITH SOAP & WATER.  
INHALATION: IF OVERCOME BY VAPORS, REMOVE TO FRESH AIR & CALL A  
PHYSICIAN. INGESTION: DO NOT INDUCE VOMITING. CALL A PHYSICIAN.

=====  
===== Fire Fighting Measures =====

Flash Point Method:SCC  
Flash Point:103 F/39 C  
Lower Limits:0.9  
Upper Limits:7  
Extinguishing Media:CARBON DIOXIDE, FOAM, DRY CHEMICAL, OR WATER FOG.  
Fire Fighting Procedures:USE AIR SUPPLIED BREATHING EQUIPMENT FOR  
ENCLOSED CONTAINERS WITH WATER SPRAY. AVOID BREATHING VAPOR OR  
FUMES.  
Unusual Fire/Explosion Hazard:IF LEAK OR SPILL HAS IGNITED, USE WATER  
SP

RAY TO DISPERSE THE VAPORS FROM FIRE FIGHTERS.

===== Accidental Release Measures =====

Spill Release Procedures: REMOVE ALL SOURCES OF IGNITION, KEEP FROM HEAT, SPARKS & OPEN FLAMES, ADD ABSORBENT (SAND, EARTH, SAWDUST) TO SPILL. VENTILATE AREA (OPEN WINDOWS, DOORS) LARGE SPILL: KEEP PRODUCT FROM ENTERING SEWERS & WATERCOURSES BY DIKING, ADVISE AUTHORITIES.

===== Handling and Storage =====

Handling and Storage Pre

cautions: STORE AWAY FROM IGNITION SOURCES. KEEP

IN COOL, DRY VENTILATED AREA. AVOID DIRECT SUNLIGHT AND EXTREME TEMPERATURES, HOT OR COLD.

Other Precautions: AVOID EYE, SKIN CONTACT, INHALATION, INGESTION OF MISTS, SPRAY OR VAPORS. AVOID BREATHING SANDING OR BLASTING DUST.

===== Exposure Controls/Personal Protection =====

Respiratory Protection: USE HYDROCARBON VAPOR CANISTER OR SUPPLIED AIR RESPIRATOR IN CONFINED AREAS.

Ventilation: LOCAL EXHAUST FACE VELOCITY 6

0PPM. SPECIAL USE ONLY WITH

ADEQUATE VENTILATION. MECHANICAL USE EXPLOSION PROOF EQUIPMENT.

Protective Gloves: CHEMICAL RESISTANT.

Eye Protection: CHEMICAL SPLASH GOGGLES/FACE SHIELDS.

Other Protective Equipment: USE CHEMICAL RESISTANT APRON OR CLOTHING.

Supplemental Safety and Health

AVOID EYE, SKIN CONTACT, INHALATION, INGESTION OF MISTS, SPRAY OR VAPORS. AVOID BREATHING, SANDING OR BLASTING DUST.

===== Physical/Chemical Properties =====

Boiling Pt: B.P. Text:

308 F/153 C

Vapor Pres: