View NSN Online: https://aerobasegroup.com/nsn/8040-00-270-8137

BF GOODRICH THE ADHESIVE PRODUCTS DIV -- 3010370, A-1177-B-1 TWO PART EPOXY -- 8040-00-270-8137

Product ID:3010370, A-1177-B-1 TWO PART EPOXY

MSDS Date:03/10/1993

FSC:8040

NIIN:00-270-8137

Kit Part:Y

MSDS Number: BNCBP === Responsible Party ===

Company Name: BF GOODRICH THE ADHESIVE PRODUCTS DIV

Address:500 MAIN ST

City:AKRON State:OH ZIP:44318 Country:US Info Ph

one Num:216-374-3000 / FAX 216-374-2333

Emergency Phone Num:216-374-3000 Preparer's Name:CLIFFORD PEARSON

CAGE:1HS43

=== Contractor Identification ===

Company Name: PIEDMONT POLYMERS INC

Address:5025 S ROYAL ATLANTIC DR

Box:188 City:TUCKER State:GA ZIP:30084

Phone: 404-939-5660

CAGE:0GGS8

Country:US

Company Name: SIA ADHESIVES INC

Address:123 W BARTGES ST

Box:City:AKRON

State:OH

ZIP:44311-1081 Country:US

Phone:330-374-2786 / 330-374-2900

CAGE:1HS43

====== Composition/Information on Ingredi

ents ========
Ingred Name:NO INGREDIENT FOR THIS FORMULATION_INGREDIENT
======================================
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:SOME PEOPLE MAY DEVELOP ALLERGIC REACTION.
Explanation of Carcinogenicity:NONE KNOWN. Effects of Overexposure:MINOR TRANSIENT IRRITATION OF EYES AND SKIN. Medical Cond Aggravated by Exposure:SKIN RASHES.
======================================
First Aid:FLUSH EYE WITH WATER FOR 15 MINUTES HOLDING EYE LIDS OPEN. SEE A PHYSICIAN. WASH SKIN WITH SOAP AND WATER. SEE A PHYSICIAN IF RASH DEVELOPS. REMOVE TO FRESH AIR. GIVE ARTIFICIAL RESPIRATION IF NOT BRE ATHING. CONSULT A PHYSICIAN.
======================================
Extinguishing Media:WATER, CARBON DIOXIDE, FOAM, DRY CHEMICAL. Fire Fighting Procedures:DO NOT ENTER CONFINED FIRE SPACE WITHOUT PROPER PROTECTIVE EQUIPMENT, INCLUDING A NIOSH APPROVED SELF-CONTAINED BREATHING APPARATUS. Unusual Fire/Explosion Hazard:TOXIC FUMES POSSIBLE.
========= Accidental Release Measures ==========
Spill Release Procedures:AVOID EYE AND SKIN CONTACT. SCRAPE UP OR ABSORB AND PLACE IN CONTAINER FOR DISPOSAL.
======================================
Handling and Storage Precautions:STORE IN A COOL, DRY AREA, AWAY FROM SOURCES OF HEAT. KEEP AWAY FROM CHILDREN.

=== Exposure Controls/Personal Protection =======
Respiratory Protection:NOT NORAMLLY NECESSARY. USE ORGANIC VAPOR FOR FUMES FROM HEATED MATERIAL. Ventilation:LOCAL AT A POINT OF CORE OR HEATING. Protective Gloves:NEOPRENE Eye Protection:GOGGLES Other Protective Equipment:EYE WASH AND SHOWER IN AREA. Supplemental Safety and Health KEY1:T6.
========= Physical/Chemical Properties =========
HCC:N1 NRC/State Lic Num:NONE Vapor Density:>1 Spec Gravity:1.37 Viscosity :>100,000 CPS Appearance and Odor:VERY VISCOUS LIQUID WITH EPOXY ODOR Percent Volatiles by Volume:NONE
========= Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES ACID, BASE Stability Condition to Avoid:AMINE COMPOUNDS IN UNCONTROLLED CONDITIONS Hazardous Decomposition Products:CARBON DIOXIDE, CARBON MONOXIDE, PHENOL AND OTHER TOXIC FUMES.
======= Disposal Considerations ==========
Waste Disposal Methods:THIS MAT ERIAL IF DISCARDED MAY BE HAZARDOUS. DISCARD IN ACCORDANCE WITH FEDERAL, STATE & LOCAL REGULATIONS. INCINERATION IS THE PREFERRED METHOD.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document

should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.