View NSN Online: https://aerobasegroup.kr/nsn/5330-00-551-1491

## 

Product ID:ASBESTOS FILLED FLEXSEAL GASKET

MSDS Date:04/15/1991

FSC:5330

NIIN:00-551-1491

MSDS Number: BQDZJ === Responsible Party ===

Company Name: FURON CO, METALLIC GASKET DIV

Address:1977 KINDRED ST

City:HOUSTON

State:TX ZIP:77049 Country:US

Info Phone Num:800-972-7638

Emergen

cy Phone Num:713-458-5830

CAGE:4V062

=== Contractor Identification ===

Company Name: FURON CO, METALLIC GASKET DIV

Address:1977 KINDRED ST

Box:City:HOUSTON

State:TX ZIP:77049 Country:US

Phone:713-458-5830

CAGE:4V062

======= Composition/Information on Ingredients ========

Ingred Name: ASBESTOS, CHRYSOTILE (CONFINED BETWEEN METAL PLIES)

CAS:12001-29-5 RTECS #:CI6478500

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.2 FIBERS/CC

ACGIH TLV:2 FIBERS/CC; A1;9293

====== Hazar

ds Identification ==========

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO

Health Hazards Acute and Chronic:ACUTE- NONE UNDER NORMAL CONDITIONS OF USE. GRINDING, SANDING/MACHINING MAY PRODUCE NUISANCE PARTICULATES THAT CAN CAUSE IRRITATION OF EYES, SKIN, GI TRACT & RESPIRATORY PASSAGES. CHRONIC- LONG TERM E XPOSURE TO ASBESTOS CAN CAUSE IRREVERSIBLE ASBESTOSIS. LUNG DISEASE & LUNG CANCER. SMOKING

## GREATLY INCREASES THE RISKS.

Explanation of Carcinogenicity: ASBESTOS IS REGULATED BY OSHA AS A CARCINOGEN.

Effects of Overexposure:NONE UNDER NORMAL CONDITIONS OF USE.HOWEVER,GRINDING,SANDING/MACHINING MAY PRODUCE NUISANCE PARTICULATES THAT CAN CAUSE IRRITATION OF EYES,SKIN,GI AND RESPIRATORY TRACTS.MAY CAUSE NAUSEA,VOMITING AND DIARRHEA.MAY CAUSE LABORED BREATHING,CHEST PAIN & TIGHTNESS.SYMPTOMS ARE NOT USUALLY MANIFEST UNTIL 15-20 YEARS LATER.

## Medical Cond Aggravated

by Exposure:PERSONS WITH PRE-EXISTING SKIN
DISORDERS SUCH AS DERMATITIS, RESPIRATORY PROBLEMS, LUNG DISEASE,
BRONCHIAL HYPER-REACTIVITY OR ANY CONDITION THAT MAY BE AGGRAVATED
BY NUISANCE DUST OR FIBERS.

First Aid:SEEK MEDICAL ATTENTION IF SYMPTOMS DEVELOP. IN CASE OF EYE IRRITATION GENTLY RINSE WITH WATER FOR 15 MINUTES WHILE KEEPING EYELIDS OPEN. DO NOT RUB EYES. SKIN: WASH FREQUENTLY WITH SOAP AND W

ATER. INH ALATION: REMOVE TO FRESH AIR. INGESTION: DO NOT INDUCE VOMITING. SEE A PHYSICIAN.


============= Fire Fighting Measures ========================

## Flash Point:NONE

Extinguishing Media: WILL NOT SUPPORT COMBUSTION.

Fire Fighting Procedures:AVOID BREATHING FUMES. WEAR PROTECTIVE CLOTHING AND NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS OPERATED IN THE POSITIVE PRESSURE MODE (HMIS).

Unusual Fire/Explosion Hazard: ASBESTOS FIBERS MAY BE RELEASED. MATERIAL MAY BURN



Stability Indicator/Materials to Avoid:YES
NONE KNOWN
Stability Condition to Avoid: AVOID INHALATION OR INGESTION OF DUST.
Hazardous Decomposition Products: ASBESTOS FIBERS MAY BE RELEASED
MATERIAL MAY BURN WITH DIFFICULTY & MAY EMIT TOXIC RUBBER

==== Stability and Reactivity Data ========

COMBUSTION PRODUCTS.

======= Disposal Considerations ===========

Waste Disposal Methods:APPROVED LANDFILL. WASTE SHOULD BE CONTAINED IN IMPERMEABLE BAGS, LABEL ED AND DISPOSED IN ACCORDANCE WITH ALL LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume r

esponsibility for the suitability of this information to their particular situation.