View NSN Online: https://aerobasegroup.kr/nsn/3439-00-056-0034

## STELLITE COATINGS -- STELLITE 6, P1060 -- 3439-00-056-0034

Product ID:STELLITE 6, P1060

MSDS Date:01/15/1991

FSC:3439

NIIN:00-056-0034

MSDS Number: BSYJF === Responsible Party ===

Company Name: STELLITE COATINGS Address: 1201 EISENHOWER DR NORTH

Box:807

City:GOSHEN

State:IN

ZIP:46526-5396

Country:US

Info Phone Num:219-534-2585

Emergency Phone Num:219-534-2585

CAGE: STELL

=== Contractor Identification ===

Company Name: STELLITE COATINGS Address: 1201 EISENHOWER DR NORTH

Box:807

City: GOSHEN

State:IN

ZIP:46526-5396

Country:US

Phone:219-534-2585

CAGE:STELL

======= Composition/Information on Ingredients ========

Ingred Name:BORON

CAS:7440-42-8

RTECS #:ED3750000

OSHA PEL:N/K ACGIH TLV:N/K

Ingred Name: CARBON

CAS:7440-44-0

RTECS #:FF5250100 Fraction by Wt: 1.15%

OSHA PEL:10 MG/M3 TDUST ACGIH TLV:2 MG/M3 TDUST

Ingred Name: COBALT (SARA III)

CAS:744

0-48-4

RTECS #:GF8750000 Fraction by Wt: BALANCE OSHA PEL:0.05 MG/M3

ACGIH TLV:0.05 MG/M3 DUST

Ingred Name: CHROMIUM (SARA III)

CAS:7440-47-3

RTECS #:GB4200000 Fraction by Wt: 27.75% OSHA PEL:1 MG/M3 ACGIH TLV:0.5 MG/M3

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: COPPER (SARA III)

CAS:7440-50-8

RTECS #:GL5325000

OSHA PEL:0.1MG/M3 FUME;1 DUST ACGIH TLV:0.2MG/M3 FUME;1 DUST

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:IRON (III) OXIDE; (IRON OXIDE)

CAS:1309-37-1

RTECS #:NO7400000

Fr

action by Wt: 3% (MAX) OSHA PEL:10 MG/M3 (FE) ACGIH TLV:5 MG/M3 (FE)

Ingred Name: MANGANESE (SARA III). TLV:5 MG/M3 DUST;3 MG/M3 FUME STEL.

CAS:7439-96-5

RTECS #:OO9275000 Fraction by Wt: 1% (MAX)

OSHA PEL:5 MG/M3 DUST, 5 C

ACGIH TLV:SEE INGREDIENT NAME

Ingred Name: MOLYBDENUM

CAS:7439-98-7

RTECS #:QA4680000 Fraction by Wt: 1% (MAX) OSHA PEL:10 MG/M3 TDUST

ACGIH TLV:10 MG/M3

Ingred Name: NICKEL (SARA III)

CAS:7440-02-0

RTECS #:QR5950000 Fraction by Wt: 3% (MAX) OSHA PEL:1 MG/M3

ACGIH TLV:1 MG/

Ingred Name: SILICON

CAS:7440-21-3

RTECS #:VW0400000 Fraction by Wt: 1.15%

OSHA PEL:10MG/M3 TDUST;5 RESP

ACGIH TLV:10MG/M3 TDUST

Ingred Name: VANADIUM (SARA III)

CAS:7440-62-2

RTECS #:YW1355000 Fraction by Wt: 4.5%

OSHA PEL:0.05 MG/M3 (V205) ACGIH TLV:0.05 MG/M3 (V205)

Ingred Name:TUNGSTEN

CAS:7440-33-7

RTECS #:YO7175000

OSHA PEL:5 MG/M3;10 STEL ACGIH TLV:5 MG/M3;10 STEL

Ingred Name:SUPDAT:MONOGRAPHS ON THE EVALUATION OF CARCINOGENIC RISK OF CHEMICALS TO MAN, VOL 52, PG 363, 1991:GRP 2

В.

RTECS #:9999999ZZ

Ingred Name:FIRST AID PROC:MED ASSISTANCE. EYES:FLUSH W/COPIOUS AMTS OF CLEAN WATER FOR AT LST 15 MINS. IF IRRIT PERSISTS (ING 15) RTECS #:9999999ZZ

Ingred Name:ING 14:OBTAIN MED ASSISTANCE. CONT LENSES SHOULD NOT BE WORN IF WORKING W/METAL DUSTS/PWDRS. MED SURVEILLANCE: (ING 16) RTECS #:9999999ZZ

Ingred Name:ING 15:LUNG FUNCTION TESTS, CHEST X-RAYS & ROUTINE PHYSICAL EXAMS MAY BE USEFUL TO DETERMINE EFTS OF DUST/FUME EXPOSURE. RTECS #:9999999ZZ

Ingred Name:S

PILL PROC:IN WASTE CNTNR. METAL PWDRS/DUSTS MAY HAVE SIGNIFICANT IMPACT ON AIR & WATER QUALITY. AIRBORNE (ING 18) RTECS #:9999992Z

Ingred Name:ING 17:EMISSIONS, SPILLS & RELS TO ENVIRON (DISCHARGE TO STREAMS, SEWER SYS, GROUND WATER, SURF SOIL, ETC) (ING 19) RTECS #:9999999ZZ

Ingred Name:ING 18:SHOULD BE CONTROLLED IMMED. IF SUCH POTNTL FOR SPILL/RELS EXISTS IT IS ADVISABLE TO DEVELOP EMER SPILL (ING 20) RTECS #:9999999ZZ

Ingred Name:ING 19:RESPONSE PLAN. RTECS #:9999999ZZ

Ingre

d Name: OTHER PREC: SOURCES OF IGNITION.

RTECS #:9999999ZZ

Ingred Name: VENT: TO ELEMENTS IDENTIFIED IN ING SECTION CAN BE BEST DETERMINED BY HAVING AIR SAMPLES TAKEN IN EMPLOYEE BRTHG (ING 23) RTECS #:9999999ZZ

Ingred Name:ING 22:ZONE, WORK AREA OR DEPARTMENT. RTECS #:9999999ZZ

Ingred Name:OTHER PROT EQUIP:APPROPRIATE TO CIRCUMSTANCES OF EXPOSURE. RTECS #:9999999ZZ

=========== Hazards Identification ==========================

LD50 LC50 Mixture: NONE SPECIFIED BY MANUFACTURER.

Routes

of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO

Health Hazards Acute and Chronic:INHAL:DUST, FUME OR POWDER MAY RESULT FROM THERMAL SPRAYING, WELDING, METALLIZING OR SIMILAR OPERATIONS WHICH GENERATE AIRBORNE METAL PARTICULATE. SKIN:CONTACT W/THIS MATERIAL MAY CAUSE, IN SOME SENSI TIVE INDIVIDUALS ALLERGIC RESPONSE IF ELEMENTS SUCH AS CHROMIUM, COBALT, COPPER & NICKEL ARE PRESENT. (EFTS OF OVEREXP)

**Explanation of Carcin** 

ogenicity:CHROMIUM:IARC MONOGRAPHS, VOL 49, PG 49, 1990:GRP 1. NTP 7TH ANNUAL RPT ON CARCINS, 1992:KNOWN TO BE CARCIN. (SUPP DATA)

Effects of Overexposure:HLTH HAZ:IN FORM OF METAL OR POWDER, CONTACT OR ABRASION MAY ALSO CAUSE IRRITATION OR DERMATITIS. EYES:PARTICULATE METAL (DUST, FUME OR POWDER) MAY BE DANGEROUS TO EYE & SURROUNDING TISSUE. CONTACT NE HC FOR FURTHER INFORMATION.

Medical Cond Aggravated by Exposure: NONE SPECIFIED BY MANUFACTURER.

| =============     | =======  | F     |      |     |     |
|-------------------|----------|-------|------|-----|-----|
| irst Aid Measures | ======== | ===== | ==== | === | === |

First Aid:INHAL:BRTHG DFCLTY REQS REMOVAL TO FRESH AIR. IF BRTHG HAS STOPPED, PERFORM ARTF RESP & OBTAIN MED ASSISTANCE AT ONCE. INGEST:CAN BE TREATED BY HAVING AFFECTED PERS SWALLOW LG QTYS OF WATER & ATTEMPTI NG TO INDUCE VOMIT IF CONSCIOUS. OBTAINMED ASSISTANCE AT ONCE. SKIN:CUTS & ABRASIONS CAN BE TREATED BY STD FIRST AID. CONTAM CAN BE REMOVED BY WASHING W/SOAP & WATER. IF IRRIT PERSISTS OBTAIN(ING 14)

\_\_\_\_\_

= Fire Fighting Measures ==========

Flash Point:NONE Lower Limits:NONE Upper Limits:NONE

Extinguishing Media:THIS ALLOY IS NONCOMBUST. USE EXTING MEDIA APPROP TO SURROUND FIRE. TO EXTING METAL PWDR FIRE USE DRY SAND, DRY (SUPDAT)

Fire Fighting Procedures:USE NIOSH/MSHA APPRVD SCBA & FULL PROT EQUIP .

IF THIS PWDR IS ATTRITIONED/REDUCED IN PARTICLE SIZE, CAUT MUST BE USED TO PVNT FIRE BY AVOIDING (SUPDAT)

Unusual Fire/Explosion Hazard:NO UNUSUAL FIRE OR EXPLOSION HAZ ARDS ARE

ASSOCIATED W/THIS MATERIAL.

======== Accidental Release Measures ===========

Spill Release Procedures:IN PWDR/DUST FORM, CLEAN-UP SHOULD BE CONDUCTED W/VACUUM SYS UTILIZING HIGH EFFICIENCY PARTICULATE AIR FILTRATION SYS. CAUT SHOULD BE TAKEN TO MIN AIRBORN GENERATION OF PWDR/DUST & AVOID CONTAM OF AIR & WATER. PROPERLY LBL ALL MATLS COLLECTED(ING 17)

Neutralizing Agent: NONE SPECIFIED BY MANUFACTURER.

======== Handling and Storage

\_\_\_\_\_

Handling and Storage Precautions:THIS PROD MUST BE HNDLD ACCORDING TO SIZE, SHAPE & QTY OF MATL INVOLVED. PWDRS SHOULD BE MOVED/TRANSPORTED TO MIN SPILL/RELS POTNTL.

Other Precautions:STORE METAL & METAL PWDR IN DRY AREA. DO NOT STORE ADJACENT TO MINERAL ACIDS. THIS IS NOT REGARDED AS FLAMM MATL, HOWEVER, IF THIS PWDR IS ATTRITIONED/REDUCED IN PARTICULAR SIZE, CAUT SHOULD BE TAKEN TO KEEP AWAY FROM FLAMES & (ING 21)

====== Exposure Controls/
Personal Protection =======

Respiratory Protection: USE NIOSH/MSHA APPROVED RESPIRATORS AS SPECIFIED BY INDUSTRIAL HYGIENIST OR QUALIFIED SAFETY PROFESSIONAL. LUNG FUNCTION TESTS ARE RECOMMENDED FOR USERS OF NEGATIVE PRESSURE DEVICES.

Ventilation:LOC EXHST VENT SHOULD BE USED TO CONTROL EXPOS TO AIRBORNE DUST & FUME WHENEVER POSS. ENVIRON SURVEILLANCE:EXPOS(ING 22)

Protective Gloves: IMPERVIOUS GLOVES.

Eye Protection: CHEMICAL SAFETY GOGGLES.

Other Protective Equipment:PRO

T CLTHG SUCH AS UNIFORMS, DISPOSABLE

COVERALLS, SFTY SHOES, ETC MAY BE REQD DURING METAL HNDLG OPERATIONS AS (ING 24)

Work Hygienic Practices: NONE SPECIFIED BY MANUFACTURER.

Supplemental Safety and Health

EXT MEDIA:GRAPHITE/OTHER CLASS "D" FIRE EXTING PWDR. FIRE FIGHT PROC:SOURCES OF IGNIT, FLAMES, ETC. HAZ DECOMP PROD:OPERATIONS. REFER TO ING SECTION FOR PELS. EXPLAN OF CARCIN:NICKEL:IARC MONOGRAPHS, SUPP, VOL 7, PG 264, 1987:GRP 2B. NTP 7TH ANNUAL RPT ON CARCINS, 1992:

ANTIC TO BE A CARCIN. COBALT: IARC (ING 13)

========= Physical/Chemical Properties ===========

Melt/Freeze Pt:M.P/F.P Text:2475F,1357C

Spec Gravity:8.38 (H\*2O=1) Solubility in Water:NONE

Appearance and Odor:POWDER, GRAY COLOR; NO ODOR.

Percent Volatiles by Volume: NONE

======== Stability and Reactivity Data =========

Stability Indicator/Materials to Avoid:YES

AVOID CONT W/MINERAL ACIDS & OXIDIZING AGENTS WHICH MAY GENERATE HYDROGEN GAS; EVOLUTION OF HYD

## ROGEN MAY BE EXPLO HAZ.

Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER.
Hazardous Decomposition Products:VARIOUS ELEMENTAL METALS & METAL
OXIDES MAY BE GENERATED DURING THERMAL SPRAYING, WELDING,
METALLIZING/SIMILAR (SUPDAT)

======= Disposal Considerations ==========

Waste Disposal Methods:PRIOR TO DISP CONSIDER IF MATL HAS RECOVERY VALUE. LOC, STATE/FED REGS MAY REQ SPECIFIC LABELING, PACKING, STOR, TRANSPORTATION & DISP PROCS. CONT ENVIRO N ENGINEER/CONSULTANT FAMILIAR W/WASTE DISP REG S.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suit ability of this information to their particular situation.