

CLIFTON ADHESIVE INC -- FA-1030 BLACK -- 8040-00-515-2246

=====
===== Product Identification =====

Product ID:FA-1030 BLACK
MSDS Date:07/16/1987
FSC:8040
NIIN:00-515-2246
Kit Part:Y
MSDS Number: BVZGC
=== Responsible Party ===
Company Name:CLIFTON ADHESIVE INC
Address:BURGESS PL
Box:282
City:WAYNE
State:NJ
ZIP:07474-0282
Country:US
Info Phone Num:201-694-0845
Emergency Phone Num:201-694-0845
CAGE:79833

=== Contractor Identification ===
Company Name:CLIFTON ADHESIVE INC
Address:BURGESS PL
Box:City:WAYNE
State:NJ
ZIP:07470
Country:US
Phone:201-694-0845; 973-694-0845
CAGE:79833

=====
===== Composition/Information on Ingredients =====

Ingred Name:TOLUENE (SARA III)
CAS:108-88-3
RTECS #:XS5250000
Fraction by Wt: 45%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:200 PPM; Z-2
ACGIH TLV:S, 50 PPM; 9394
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

Ingred Name:HEXANE (N-HEXANE)
CAS:110-54-3
R

TECS #:MN9275000
Fraction by Wt: 31%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:500 PPM
ACGIH TLV:50 PPM; 9394
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

Ingred Name:POLYCHLOROPRENE RUBBER
CAS:9010-98-4
RTECS #:EI9460000
Other REC Limits:NONE RECOMMENDED

Ingred Name:VOLATILE ORGANIC CONTENT=65.6G/L
RTECS #:9999999VO
Other REC Limits:NONE RECOMMENDED

===== Hazards Identification =====

LD50 LC50 Mixture:TLV FOR TOLUENE IS 100PPM
Routes of Entry: Inhalation:YES Skin:YE
S Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:EYES:MAY CAUSE IRRITATION.SKIN:MAY
CAUSE IRRITATION AND DEFATTING.INGEST:MAY CAUSE GI TRACT
IRRITATION.HMIS SUGGESTS THAT ITEM MAY CAUSE LUNG DAMAGE IF VOMITED
AFTER INGESTING.INHAL:MAY CAUSE RESPIRAT ORY IRRITATION AND CNS
EFFECTS.CHRONIC:MAY CAUSE LIVER,KIDNEY,SPLEEN,NERVIOUS SYSTEM AND
BRAIN DAMAGE(TOLUENE).
Explanation of Carcinogenicity:THERE ARE NO INGREDIENTS ABOVE 0.
1%
WHICH ARE IDENTIFIED AS CARCINOGENS BY NTP,IARC OR OSHA.
Effects of
Overexposure:INHAL:NAUSEA,NARCOSIS.INGEST:VOMITING,NUMBNESS,TINGLIN
G AND WEAKNESS OF THE ARMS AND LEGS.
Medical Cond Aggravated by Exposure:PERSONS WITH PRE-EXISTING
RESPIRATORY AILMENTS MAY BE AT INCREASED RISK FROM EXPOSURE.

===== First Aid Measures =====

First Aid:SKIN:REMOVE CONTAMINATED CLOTHING;WASH WITH SOAP AND
WATER.EYES:FLUSH WITH WATER FOR 15 MINUTES.INHA

L:REMOVE TO FRESH

AIR.GIVE OXYGEN OR ARTIFICIAL RESPIRATION IF NEEDED.INGEST:DO NOT
INDUCE VOMITING. GET PROMPT QUALIFIED MEDICAL ATTENTION.

===== Fire Fighting Measures =====

Flash Point Method:TCC

Flash Point: