

MINOLTA CORPORATION,USA -- ACTIONLASER 1000/1500 S 051011 TONER -- 6850-01-411-2477
===== Product Identification =====

Product ID:ACTIONLASER 1000/1500 S 051011 TONER

MSDS Date:03/04/1993

FSC:6850

NIIN:01-411-2477

MSDS Number: BXYVM

=== Responsible Party ===

Company Name:MINOLTA CORPORATION,USA

Address:101 WILLIAMS DRIVE

City:RAMSEY

State:NJ

ZIP:07446-1217

Country:US

Info Phone Num:201-825-4000

E

mergency Phone Num:201-825-4000 OR IN JAPAN#06-2712251

CAGE:23736

=== Contractor Identification ===

Company Name:AMERICAN LASER INC

Address:1007 RIPLEY ST

Box:City:SILVER SPRING

State:MD

ZIP:20910

Country:US

Phone:301-588-4850

CAGE:0S0F8

Company Name:EPSON AMERICA, INC

Address:3840 KILROY AIRPORT WAY

Box:City:LONG BEACH

State:CA

ZIP:90806

Country:US

Phone:562-276-1369/800-859-1397

CAGE:0HAF7

Company Name:MINOLTA CORPORATION

Address:101 WILLIAMS DRIVE

Box:City:RAMSEY

State:NJ

ZIP:07446

Country:U

S

Phone:201-825-4000

CAGE:23736

=====
===== Composition/Information on Ingredients =====

Ingred Name:ALUMINUM DRUM (CARTRIDGE)

Fraction by Wt: >97%

Other REC Limits:NONE RECOMMENDED

Ingred Name:Binder Resin

Fraction by Wt: