

PRAXAIR INC -- ARGON IN THERMOMETER -- 6685-00-477-2170

===== Product Identification =====

Product ID:ARGON IN THERMOMETER

MSDS Date:12/01/1992

FSC:6685

NIIN:00-477-2170

MSDS Number: CFYMC

=== Responsible Party ===

Company Name:PRAXAIR INC

Address:39 OLD RIDGEBURY RD

City:DANBURY

State:CT

ZIP:06817-0001

Country:US

Info Phone Num:203-794-5782

Emergency Phone Num:203-794-5782

CAGE:0LV01

=== Contract

or Identification ===

Company Name:MOELLER INSTRUMENT CO

Address:126 MAIN ST

Box:668

City:IVORYTON

State:CT

ZIP:06442

Country:US

Phone:860-767-2104

CAGE:76526

Company Name:PRAXAIR, INC.

Address:39 OLD RIDGEBURY RD

Box:City:DANBURY

State:CT

ZIP:06810-5113

Country:US

Phone:800-772-9247; 800-PRAXAIR

CAGE:0LV01

===== Composition/Information on Ingredients =====

Ingred Name:ARGON

CAS:7440-37-1

RTECS #:CF2300000

Fraction by Wt: 100%

Other REC Limits:NONE RECOMMENDED

ACGIH TLV:ASPHY

=====  
===== Hazards Identification =====

LD50 LC50 Mixture:NOT RELEVANT  
Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:TARGET ORGANS:NONE. ACUTE AND CHRONIC-  
THERMOMETER CONTAINS SMALL AMOUNTS OF ARGON. NO HAZARD IS  
ANTICIPATED IN NORMAL CONDITION OF USE.  
Explanation of Carcinogenicity:NONE  
Effects of Overexposure:NONE  
Medical Cond Aggravated by Exposure:  
NONE

=====  
===== First Aid Measures =====

First Aid:INHALED:MOVE TO FRESH AIR.

=====  
===== Fire Fighting Measures =====

Flash Point:NONE  
Lower Limits:NOT RELEVANT  
Upper Limits:NOT RELEVANT  
Extinguishing Media:USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY  
CHEMICAL FOR SURROUNDING FIRE.  
Fire Fighting Procedures:WEAR NIOSH-APPROVED SELF-CONTAINED BREATHING  
APPARATUS IF NEEDED.  
Unusual Fire/Explosion Hazard:THERMOMETER MAY RUPTURE  
DUE TO HEAT OF  
FIRE.

=====  
===== Accidental Release Measures =====

Spill Release Procedures:VENTILATE AREA.  
Neutralizing Agent:NOT RELEVANT

=====  
===== Handling and Storage =====

Handling and Storage Precautions:HANDLE WITH CARE. KEEP OUT OF REACH OF  
SMALL CHILDREN.  
Other Precautions:WASH HANDS AFTER HANDLING.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE SHOULD BE NEEDED.  
Ventilat

ion:NONE SHOULD BE NEEDED.

Protective Gloves:NONE SHOULD BE NEEDED.

Eye Protection:SAFETY GLASSES RECOMMENDED

Other Protective Equipment:NONE SHOULD BE NEEDED.

Work Hygienic Practices:OBSERVE GOOD INDUSTRIAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES.

Supplemental Safety and Health

THIS IS A THERMOMETER WHICH HAS SMALL AMOUNTS OF ARGON GAS.

===== Physical/Chemical Properties =====

HCC:G3

NRC/State Lic Num:NOT RELEVANT

Boiling Pt:B.P. Text:-303F,-186C

Melt/Free

ze Pt:M.P/F.P Text:-309F,-189C

Vapor Density:1.378

Spec Gravity:GAS

Viscosity:NOT RELEVANT

Evaporation Rate & Reference:NOT RELEVANT

Solubility in Water:NEGLIGIBLE

Appearance and Odor:COLORLESS, ODORLESS GAS

Percent Volatiles by Volume:100

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

Stability Condition to Avoid:EXCESSIVE HEAT

Hazardous Decomposition Products:NONE

===== Disposal Considerations =====

=====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice t

o verify and  
assume responsibility for the suitability of this information to their  
particular situation.