Product ID: EPK 0150 PART B MSDS Date:05/20/1988 FSC:6080 NIIN:01-358-9686 Status Code:A Kit Part:Y **MSDS Number: CJGPB** === Responsible Party === Company Name: DEXTER HYSOL AEROSPACE INC DIV OF EXTER CORP Address:2850 WILLOW PASS ROAD Box:312 City:PITTSBURG State:CA ZIP:94565-3237 Co untry:US Info Phone Num:510-458-8000 Emergency Phone Num:415-687-4201 CAGE:33564 === Contractor Identification === **Company Name: DEXTER CORPORATION ADHESIVE & COATING SYSTEMS** Address:2850 WILLOW PASS ROAD Box:312 **City:BAY POINT** State:CA ZIP:94565-3299 Country:US Phone:202-483-7616 CAGE:33564 Company Name:LUCENT TECHNOLOGIES Address:2000 NE EXPY **Box:UNKNOW** City:NORCROSS State:GA ZIP:30071 Country:US Phone:770-798-3846 CAGE:1K705

Ingred Name:SILICA CAS:7631-86-9 &It; Wt:5. OSHA PEL:20 MPPCF

Ingred Name:TRIETHYLENETETRAMINE CAS:112-24-3 RTECS #:YE6650000 &It; Wt:30.

LD50 LC50 Mixture:NONE SPECIFIED BY MANUFACTURER Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:MATERIAL IS CORROSIVE TO SKIN. MAY CAUSE CHEMICAL BURN TO EYES AND SKIN. REPEAT CONTACT MAY CAUSE SENSITIZATION. Explanation of Carcinogenicity:NONE SPECIFIED BY MANUFACTURER Effects of Overexposure: POSSIBLE BURNS TO EYES AND SKIN, IRRITATION AND POSSIBLE SENSITIZATION TO SKIN. Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER First Aid: FLUSH SKIN AND EYES WITH PLENTY OF WATER. WASH SKIN THOROUGHLY WITH SOAP 7 WATER, RUBBING ALCOHOL OR HAND CLEANER. DO NOT USE SOLVENTS. REMOVE SOILED CLOTHES AND WASH BEFORE REUSE. IF **IRRITATION PERSI STS, SEE PHYSICIAN.** Flash Point Method:COC Flash Point:=129.4C, 265.F Extinguishing Media: DRY CHEMICAL OR HALON FIRE EXTINGUISHER, OR WATER SPRAY, FOAM, FOG Fire Fighting Procedures: USE SELF-CONTAINED BREATHING APPARATUS WHEN FIGHTING FIRES IN CONFINED AREAS. Unusual Fire/Explosion Hazard: DENSE SMOKE AND TOXIC GASES MAY BE LIBERATED. ====== Acci

dental Release Measures ==============

Spill Release Procedures:WEAR PROTECTIVE CLOTHES, GLOVES AND SAFETY GLASSES. SCRAPE UP AND TRANSFER TO METAL CONTAINER. WIPE UP REMAINING RESIDUE WITH SOLVENTS, OBSERVING SOLVENT FLAMMABILITY CAUTIONS.

Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER

Handling and Storage Precautions: KEEP COOL IN ACCORDANCE WITH LABEL INSTRUCTIONS. STORE AT ROOM TEMPERATURE (70 DEG F) FOR 12 MONTHS.

Other Precautions: FOLLOW RECOMMENDED CURING SCHEDULE.

Respiratory Protection:NOT NEEDED WITH GOOD INDUSTRIAL VENTILATION. Ventilation:LOCAL EXHAUST RECOMMENDED. Protective Gloves:IMPERVIOUS PLASTIC OR RUBBER Eye Protection:SAFETY GLASSES OR GOGGLES Other Protective Equipment:AS NEEDED TO PROTECT SKIN AND CLOTHING Work Hygienic Practices:NONE SPECIFIED BY MANUFACTURER Supplemental Safety and Health NONE SPECIFI ED BY MANUFACTURER. KEY1=B2.

HCC:B2 Boiling Pt:=277.2C, 531.F Vapor Pres:1 Spec Gravity:0.98 Evaporation Rate & amp; Reference: