

GATES ENGINEERING CO., INC -- GACO N-700-A BLACK -- 8030-00-145-0111

=====
Product Identification
=====

Product ID:GACO N-700-A BLACK

MSDS Date:01/01/1985

FSC:8030

NIIN:00-145-0111

MSDS Number: BDCCS

=== Responsible Party ===

Company Name:GATES ENGINEERING CO., INC

Address:100 S. WEST STREET

City:WILMINGTON

State:DE

ZIP:19801

Country:US

Info Phone Num:302-656-9951

Emergency Phone Num:302-656-9951

CAGE:88112

=== Contractor Identification ===

Company Name:GATES ENGINEERING CO.,INC.

Address:100 S. WEST STREET

Box:City:WILMINGTON

State:DE

ZIP:19801

Country:US

Phone:.....DISCONNECTED....

CAGE:88112

=====
Composition/Information on Ingredients
=====

Ingred Name:TOLUENE (SARA III)

CAS:108-88-3

RTECS #:XS5250000

OSHA PEL:200 PPM/150 STEL

ACGIH TLV:50 PPM; 9293

EPA Rpt Qty:1000 LBS

DOT Rpt Qty:1000 LBS

Ingred Name:XYLENES (O-,M-,P- ISOMERS) (SARA III)

CAS:1330-20-7

RTECS #:

ZE2100000
OSHA PEL:100 PPM/150 STEL
ACGIH TLV:100 PPM/150STEL;9192
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

Ingred Name:PETROLEUM DISTILLATES (NAPHTHA OR RUBBER SOLVENT)
CAS:8002-05-9
RTECS #:SE7449000
OSHA PEL:400 PPM
ACGIH TLV:400 PPM; 8990

=====
===== Hazards Identification =====

Effects of Overexposure:INH:ANESTHETIC. IRRIT OF RESP. TRACT, HEADACHE,
DIZZ, UNCONSCIOUSNESS. SKIN & EYE: PRIMARY IRRITANT.

=====
===== First Aid Measures =====

First Aid:FUMES: REMOVE TO FRESH AIR, RESTORE BREATHING, KEEP WARM &
QUIET, CALL PHYSICIAN. EYES:FLUSH IMMEDIATELY W/LG AMT OF WATER, 15
MIN. TAKE TO A PHYSICIAN. SKIN: WASH W/PLENTY OF WATER. REMOVE
CONTAMINATED CLOTHING. CONSULT PHYSICIAN.

=====
===== Fire Fighting Measures =====

Flash Point:40F
Lower Limits:0.9
Upper Limits:7.0
Extinguishing Media:DRY CHEMICAL, CO*2, FOAM
Fire Fighting Procedures:SELF-CONTAINED BREATHING APPARATUS &

PROTECTIVE CLOTHING
Unusual Fire/Explosion Hazard:PRODUCTS OF COMBUSTION MAY INCLUDE
CHLORINE & PHOSGENE.

=====
===== Accidental Release Measures =====

Spill Release Procedures:ABSORB & DISPOSE OF IN ACCORDANCE W/LOCAL
REGULATIONS. REMOVE ALL SOURCES OF IGNITION & VENTILATE AREA.

=====
===== Handling and Storage =====

Handling and Storage Precautions:STORE IN A COOL DRY PLACE, USE ONLY
W/ADEQUATE VETILATION. AVOID FLAMES, SPAR

KS, HOT SURFACES & STRONG
OXIDIZERS.

Other Precautions:DO NOT TAKE INTERNALLY. AVOID CONTACT W/EYES & SKIN.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:USED APPROVED RESP. DEVICE IN CONFINED AREAS.

Ventilation:USE LOCAL & MECHANICAL VENT.

Protective Gloves:YES

Eye Protection:YES

Supplemental Safety and Health

VAPOR DENSITY IS >1.0. COMBINED, THE SOLVETS ARE 63% OF THE PRODUCT,
PIGMENTS ARE 16% & THE VEHICLE IS 21%. TLV ASSIGNED BY MFG.

==

=====
===== Physical/Chemical Properties =====

HCC:F3

Spec Gravity:0.9900

Evaporation Rate & Reference: