

AMERICAN GAS AND CHEMICAL COMPANY,LTD -- DD-60B (PRE 1/1988) -- 6850-00-145-0255

===== Product Identification =====

Product ID:DD-60B (PRE 1/1988)

MSDS Date:01/01/1987

FSC:6850

NIIN:00-145-0255

Kit Part:Y

MSDS Number: BDCFC

=== Responsible Party ===

Company Name:AMERICAN GAS AND CHEMICAL COMPANY,LTD

Address:220 PEGASUS AVENUE,

City:NORTHVALE

State:NJ

ZIP:07647-1904

Country:US

Info Phone Num:800-5

26-1008

Emergency Phone Num:201-767-7300

CAGE:03530

=== Contractor Identification ===

Company Name:AMERICAN GAS AND CHEMICAL COMPANY,LTD

Address:220 PEGASUS AVENUE,

City:NORTHVALE

State:NJ

ZIP:07647-1904

Country:US

Phone:201-767-7300

CAGE:03530

===== Composition/Information on Ingredients =====

Ingred Name:NAPHTA (PETROLEUM SPIRITS OR BENZIN)

CAS:8030-30-6

RTECS #:DE3030000

Fraction by Wt: 64.6%

OSHA PEL:100 PPM

Ingred Name:AUTOMATE RED DYE

Fraction by Wt: 2.0%

ACGIH TLV:100

PPM

Ingred Name:DICHLORODIFLUOROMETHANE (SARA III)

CAS:75-71-8

RTECS #:PA8200000

Fraction by Wt: 33.3%

OSHA PEL:1000 PPM

ACGIH TLV:1000 PPM; 9192

EPA Rpt Qty:5000 LBS

DOT Rpt Qty:5000 LBS

Ozone Depleting Chemical:1

=====
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES

Effects of Overexposure:INHALED:HIGH VAPOR CONC.MAY RESULT IN SYMPTOMS FROM MILD DEPRESS. CONVULSIONS TO UNCONSCIOUSNESS.

=====
===== Fi

rst Aid Measures =====

First Aid:SKIN:WASH WITH SOAP & WATER.EYES:FLUSH WITH WATER.INGESTION:DON'T INDUCE VOMITING.INHALATION:REMOVE TO FRESH AIR.GIVE CPR/OXYGEN IF NEEDED.KEEP WARM & QUIET.REMOVE CONTAMINATED CLOTHING.NEVER GIVE ANY THING BY MOUTH TO UNCONSCIOUS PERSON.

=====
===== Fire Fighting Measures =====

Flash Point Method:TCC

Flash Point:FLAMMABLE AEROSL

Lower Limits:0.9

Upper Limits:6.0

Extinguishing Media:CARBON DIOXIDE,FOAM ,DRY CHEM & WATER FOG OR SPRAY.

Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS AND USE WATER SPRAY TO COOL CONTAINER.

Unusual Fire/Explosion Hazard:COMBUSTIBLE LIQUID.DO NOT STORE OR MIX STRONG OXIDANTS.

=====
===== Accidental Release Measures =====

Spill Release Procedures:REMOVE IGNITION SOURCES,VENTILATE AREA WELL.ABSORB WITH VERMICULITE OR OTHER MATERIALS, SUCH AS SAWDUST,RAGS,PAPER & PLACE IN CLOSED CONTAINER. USE NON SPARKING TO

OLS. WEAR PROPER PROTECTIVE EQUIPMENT DURING CLEAN UP.

=====
===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL,DRY,WELL VENT,LOW FIRE RISK AREA. PROTECT FROM PHYSICAL DAMAGE.AVOID ANY PHYSICAL CONTACT. KEEP CONTAINERS TIGHTLY CLOSED.

Other Precautions:WARNING:COMBUSTIBLE.AVOID PROLONGED OR REPEATED CONTACT.REMOVE CONTAMINATED CLOTHING.WASH SKIN WITH SOAP & WATER AFTER CONTACT.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:HYDROCARBON VAPOR CANISTER OR SUPPLIED AIR HOSE MASK IF NEEDED.

Ventilation:LOCAL EXHAUST-FACE VELOCITY 60 FPM.MECH-EXPLOS PROOF EQUIP.

Protective Gloves:IMPERVIOUS

Eye Protection:SAFETY GLASSES

Other Protective Equipment:HYDROCARBON-INSOLUBLE APRON IF NEEDED.

Supplemental Safety and Health

KEY1:F1. THIS PRODUCT IS A KIT CONSISTING OF THREE PARTS.

CLEANER/REMOVER HAS PNI A, PENETRANT HAS PNI B AND DEVELOPER HAS PNI C, SAME NSN.

====

=====
===== Physical/Chemical Properties =====

HCC:V3

NRC/State Lic Num:NOT RELEVANT

Boiling Pt:B.P. Text:313-347F

Vapor Pres: