

ELECTRICAL UTILITIES CO -- 1A9Z10301 -- 5910-00-146-4793

===== Product Identification =====

Product ID:1A9Z10301  
MSDS Date:01/01/1985  
FSC:5910  
NIIN:00-146-4793  
MSDS Number: BDCJR  
=== Responsible Party ===  
Company Name:ELECTRICAL UTILITIES CO  
Address:1 INDUSTRIAL DR  
Box:97  
City:SNOW HILL  
State:NC  
ZIP:28580-0453  
Country:US  
Emergency Phone Num:NONE  
CAGE:01102

=== Contractor Identification ===

Company  
Name:CAPTRON INC  
Address:1 INDUSTRIAL DR  
Box:97  
City:SNOW HILL  
State:NC  
ZIP:28580-0453  
Country:US  
Phone:919-747-5943  
CAGE:81133  
Company Name:ELECTRICAL UTILITIES CO.  
Box:97  
CAGE:01102

===== Composition/Information on Ingredients =====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)  
CAS:1336-36-3  
RTECS #:TQ1350000  
EPA Rpt Qty:1 LB  
DOT Rpt Qty:1 LB

===== Hazards Identification =====

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,I

## NTTESTINE.CAUSES

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

### ===== First Aid Measures =====

First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.

### ===== Accidental Release Measures =====

Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.

### ===== Handling and Storage =====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.

### ===== Exposure Controls/Personal Protection =====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD  
Ventilation:LOCAL EXHAUST  
Protective Gloves:RUBBER-IMPERV  
Eye Protection:GOGGLES,FACE SHIELD  
Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT  
Supplemental Safety and Health  
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.

### ===== Physical/Chemical Properties =====

HCC:V1  
Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR

### ===== Stability and Reactivity Data =====

STRONG OXIDIZERS

### ===== Disposal Considerations =====

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH  
TE

TEMPERATURE INCINERATION. ONLY APPROVED DISPOSAL OPERATOR  
PERMITTED..

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.