PENRECO -- PENRECO AMBER -- 9150-00-250-0928 ============= Product Identification ======================== Product ID:PENRECO AMBER MSDS Date:01/01/1987 FSC:9150 NIIN:00-250-0928 MSDS Number: BDNSX === Responsible Party === Company Name: PENRECO Emergency Phone Num: (412) 756-0110 **CAGE:PENRE** === Contractor Identification === Company Name: PENRECO Address:4401 PARK AVENUE City:DICKINSON State:TX ZIP:77539 Country:US Phone:713-236-6070 **CAGE:PENRE** Company Name: PENRECO, DIV OF PENNZOIL CO Address:700 MILIAM ST Box:2967 City:HOUSTON State:TX ZIP:77252 Country:US Phone:800-245-3952 CAGE:86459 ======= Composition/Information on Ingredients ======== Ingred Name:PETROLATUM Ingred Name: ADDITIVES (TYPE NOT SPECIFIED) ============= Hazards Identification ======================== Effects of Overexposure: NONE NOTED BY MFR. LOW TOXICITY & LOW HAZARD TO HEALTH. ====== First Aid Measur

View NSN Online: https://aerobasegroup.com/nsn/9150-00-250-0928

First Aid:SKIN:WASH W.SOAP & H*2O. EYES:FLUSH W. H*2O. INGESTED:DON'T INDUCE VOMITING. INHALED:REMOVE TO FRESH AIR. GIVE CPR/OXYGEN IF NEED. KEEP WARM & QUIET. REMOVE CONTAMINATED CLOTHING. NEVER GIVE ANYTHING BY MOUTH TO UNCONSCIOUS PERSON.

========= Fire Fighting Measures ==============

Flash Point: 400F/204.5C COC

Extinguishing Media:CO*2, FOAM, DRY CHEM.

Fire Fighting Procedures:WEAR SELF-CNTD BRTHG,APP H*20 SPRAY TO COOL CO

NTR.

Unusual Fire/Explosion Hazard: NONE NOTED BY MANUFACTURER.

======== Accidental Release Measures ===========

Spill Release Procedures:REMOVE IGNITION SOURCES, VENTILATE AREA WELL.ABSORB WITH VERMICULITE OR OTHER MATERIALS, SUCH AS SAWDUST, RAGS, PAPER & PLACE IN CLOSED CONTAINER. USE NON SPARKING TOOLS. WEAR PROPER PROTECTIVE EQUIPMENT DURING CLEAN UP.

========== Handling and Storage ==============

Handling and Storage Precautions: STORE IN

COOL, DRY, WELL VENTILATED

AREA. PROTECT FROM PHYSICAL DAMAGE.AVOID ANY PHYSICAL CONTACT. KEEP CONTAINERS TIGHTLY CLOSED

Other Precautions:DO NOT BREATHE VAPOR/MIST.DO NOT TRANSFER TO UNMARKED CONTAINERS.

====== Exposure Controls/Personal Protection ========

Respiratory Protection: USE HALF-MASK OR FULL FACE PIECE RESP FOR LOW CONC MIST

Ventilation: NO SPECIAL REQUIREMENTS W ADEQUATE VENT.

Protective Gloves: RUBBER/PLASTIC

Eye Protection: GOGGLES/FACE SHIELD

Other Prot

ective Equipment:NORMAL WORK CLOTHING COVERING ARMS & LEGS
Supplemental Safety and Health
ED (REVISED):OCTOBER 1984; SPEC REFERENCE:VV-P-236A.

======== Physical/Chemical Properties ==========

HCC:V6

NRC/State Lic Num:MSDS FM MFR DAT

Boiling Pt:B.P. Text:650F/343.5C

Vapor Pres: