View NSN Online: https://aerobasegroup.kr/nsn/6550-00-283-3206

CIBA CORNING DIAGNOSTICS CORP -- 477068 PH 6.838 BUFFER -- 6550-00-283-3206

Product ID:477068 PH 6.838 BUFFER MSDS Date:05/13/1991 FSC:6550 NIIN:00-283-3206 MSDS Number: BDTJM === Responsible Party === Company Name: CIBA CORNING DIAGNOSTICS CORP Address:63 NORTH ST City:MEDFIELD State:MA ZIP:02052-2308 Country:US Info Phone Num:508-359-7711 / FAX 508-359-2879 Eme rgency Phone Num:508-359-7711/800-888-8372(> 5PM) CAGE:51404 === Contractor Identification === Company Name: CIBA CORNING DIAGNOSTICS CORP A JOINT VENTURE Address:63 NORTH ST Box:City:MEDFIELD State:MA ZIP:02052-2308 Country:US Phone: 508-359-7711/800-255-8769 CAGE:51404

Ingred Name:NON HAZARDOUS INGREDIENTS Fraction by Wt: 100% Other REC Limits:NONE RECOMMENDED

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ACUTE: CONTACT WITH SKIN OR EYES MAY CAUSE SLIGHT IRRITATION. CHRONIC: NONE SPECIFIED BY MANUFACTURER. Explanation of Carcinogenicity:NO INGREDIENT OF A CONCENTRATION OF 0.1% OR GREATER IS LISTED AS A CARCINOGEN OR SUSPECTED CARCINOGEN. Effects of Overexposure:SKIN: IRRITATION. EYES: IRRITATION. Medical Cond Aggravated by Exposure:NONE SPECIFIED

BY MANUFACTURER.

======= First A	id Measures ====================================
First Aid:EYES-FLUSH WITH LOTS O AFFECTED AREAS WITH SOAP &	F WATER FOR 15 MINUTES. SKIN-WASH WATER.
======= Fire Fight	ing Measures ====================================
Fire Fighting Procedures:NONE SPEC	
====== Accidental Re	elease Measures ====================================
Spill Release Procedures:MOP AFFE0 Neutralizing Agent:NONE SPECIFIED	
====== Handling	and Storage ====================================
Handling and Storage Precautions:AV FREEZING.	OID HIGH TEMPERATURES & KEEP FROM
Other Precautions:NONE SPECIFIED	BY MANUFACTURER.
====== Exposure Controls/F	Personal Protection =====
EYE WASH AVAILABLE. Work Hygienic Practices:WASH HAND	RED. RUBBER, LATEX. /SIDE SHIELDS FORY PROTECTIVE CLOTHING. DLA-HMIS: DS AFTER USE AND BEFORE EATING, ER CONTAMINATED CLOTHES BEFORE REUSE

ANALYZER-6

630-01-063-2944 & 6630-01-120-8419.

HCC:N1 Boiling Pt:B.P. Text:212F,100C Melt/Freeze Pt:M.P/F.P Text:32.0F,0.0C Spec Gravity:1.01 pH:6.838 Solubility in Water:COMPLETE Appearance and Odor:ODOLESS, COLORLESS LIQUID.

Stability Indicator/Materials to Avoid:YES NONE SPECIFIED BY MANUFACTURER. Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER. Hazardo us Decomposition Products:NONE SPECIFIED BY MANUFACTURER. Conditions to Avoid Polymerization:WILL NOT OCCUR.

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or i

mplied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.