View NSN Online: https://aerobasegroup.kr/nsn/5950-00-532-1179

Product ID:1631 MSDS Date:01/01/1985 FSC:5950 NIIN:00-532-1179 MSDS Number: BFDGM === Responsible Party === Company Name: R.F. HARRIS CORP, COMMUNICATIONS DIV Address:1680 UNIVERSITY AVE City:ROCHESTER State:NY ZIP:14610-1839 Country:US Emergency Phone Num:703-739-1790 CAGE:LO536 === Contractor Identif ication === Company Name: HARRIS CORP R F COMMUNICATIONS GROUP Address:1680 UNIVERSITY AVE Box:City:ROCHESTER State:NY ZIP:14610-1839 Country:US Phone:716-244-5830 CAGE:14304 Company Name: R.F. HARRIS CORP, COMMUNICATIONS DIV Address:1680 UNIVERSITY AVE Box:City:ROCHESTER State:NY ZIP:14610-1839 Country:US CAGE:LO536

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III) CAS:1336-36-3 RTECS #:TQ1350000 EPA Rpt Qty:1 LB DOT Rpt Otv¹ I B

Qty:1 LB
======================================
Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR.GIVE ART. RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UN CONSCIOUS PERSON VOMIT.
======================================
Spill Release Procedures: USE ABSORBENT & DIKES TO PREVENT RUNOFF. ISOLATE & NOTIFY PROPER AUTHORITIES.
======================================
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
======================================
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOC AL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT. Supplemental Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.
======================================
HCC:Z3 Appearance and Odor:LIGHT STRAW0COLORED LIQUID,AROMATIC ODOR.
======================================
STRONG OXIDIZERS

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liab

ility for its use. Any person utilizing this

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.