View NSN Online: https://aerobasegroup.kr/nsn/5910-00-615-0433

CORNELL-DUBILIER ELEC.DIV. OF FED.PAC.ELEC.CO. -- TJH20005J -- 5910-00-615-0433

Product ID:TJH20005J
MSDS Date:01/01/1985
FSC:5910
NIIN:00-615-0433
MSDS Number: BFHVW
=== Responsible Party ===
Company Name:CORNELL-DUBILIER ELEC.DIV. OF FED.PAC.ELEC.CO.
Address:ONE INTERCHANGE PLZ
City:WAYNE
State:NJ
ZIP:07470
Country:US
Emergency Phone Num:580-996-8561
CAGE:14655
=== Contractor Identification ===
Company Name:CORNELL-DUBILIER ELECTRONICS
Address:ONE INTERCHANGE PLZ
Box:City:WAYNE
State:NJ
ZIP:07470
Country:US
Phone:201-694-8600
CAGE:14655
======== Composition/Information on Ingredients ====================================
Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)
CAS:1336-36-3
RTECS #:TQ1350000
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTEST

INE.CAUSES CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

======================================
First Aid:EYES:FLUSH W/WATER IMMED.SKIN:WASH W/SOAP IMMED.INHAL:REMOVE TO FRESH AIR.GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNCONSCIOUS PER SON VOMIT.
======================================
Spill Release Procedures:USE ABSORBENT & DIKES TO P REVENT
RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.
======================================
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
======================================
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT Supplem ental Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS.CAUSES STILLBIRTHS.IRRITATES EYES,NOSE,THROAT.
======================================
HCC:Z3 Appearance and Odor:LIGHT STRAW COLORED LIQUID,AROMATIC ODOR.
======================================
STRONG OXIDIZERS
======================================

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINE

RATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitabili ty of this information to their particular situation.