

CHEMICALS CO -- FLUORINE, LIQUEFIED 99% -- 9135-00-823-8122

=====
Product Identification
=====

Product ID:FLUORINE, LIQUEFIED 99%

MSDS Date:01/01/1987

FSC:9135

NIIN:00-823-8122

MSDS Number: BFRFK

=== Responsible Party ===

Company Name:CHEMICALS CO/MORRISTOWN, N.J. 07960

Address:COLUMBIA RD & PARK AVE

City:MORRISTOWN

State:NJ

ZIP:07960

Country:US

CAGE:MO054

=== Contractor Identification ===

Company

Name:ALLIED CHEMICAL INDUSTRIAL CHEM DIV

Address:COLUMBIA RD & PARK AVE

Box:City:MORRISTOWN

State:NJ

ZIP:07960

Country:US

Phone:201-455-2145

CAGE:72658

Company Name:CHEMICALS CO/MORRISTOWN, N.J. 07960

Address:COLUMBIA RD & PARK AVE

Box:City:MORRISTOWN

State:NJ

ZIP:07960

Country:US

CAGE:MO054

=====
Composition/Information on Ingredients
=====

Ingred Name:FLUORINE (SARA III)

CAS:7782-41-4

RTECS #:LM6475000

Fraction by Wt: 99%

OSHA PEL:0.1 PPM

ACGIH TLV:1 PPM/2 STEL; 9192

EPA

Rpt Qty:10 LBS
DOT Rpt Qty:10 LBS

=====
Hazards Identification
=====

Effects of Overexposure:IRRITATION OF EYES/NOSE/RESP TRACT. SEVERE
DAMAGE TO THE LUNGS/PULMONARY EDEMA/BRONCHIAL PNEUMONIA

=====
First Aid Measures
=====

First Aid:EYES: WASH WITH WATER 15 MINUTES & CALL PHYSICIAN.
INHALATION: REMOVE TO FRESH AIR. IF BREATHING HAS STOPPED, GIVE
ARTIFICIAL RESPIRATION & CALL PHYSICIAN. IF BREATHING IS DIFFICU
LT,
GIVE OXYGEN. SKIN : WASH W/WATER AT LEAST 15 MINS, CALL PHYSICIAN.

=====
Fire Fighting Measures
=====

Extinguishing Media:WATER FOG, DRY CHEMICALS
Fire Fighting Procedures:WEAR SCBA & PROTECTIVE CLOTHING.
Unusual Fire/Explosion Hazard:THE GAS FORMS EXPLOSIVE MIXTURES
W/WATER/AMMONIA/HYDROGEN/ORGANIC VAPORS/MAY IGNITE SPONTANEOUSLY.

=====
Accidental Release Measures
=====

Spill Release Procedures:EVACUATE AREA, USE MAXI
MUM VENTILATION & ALLOW
TO DISSIPATE. AREA MAY LATER BE CLEAN WITH DRY, POWDERED SODIUM
CARBONATE.

=====
Handling and Storage
=====

Handling and Storage Precautions:NON-FLAMMABLE GAS. HOWEVER, THE DOT
PLACARDS REQUIRED ARE "POISON" & "OXIDIZER."
Other Precautions:ALL PROTECTIVE EQUIPMENT SHOULD BE WASHED IMMEDIATELY
UPON CONTAMINATION. ANY CONTAMINATED NON-IMPERVIOUS CLOTHING MUST
BE ROVED IMMEDIATELY.

=====
Exposure Controls/Per
sonal Protection
=====

Respiratory Protection:THE USE OF AIR-SUPPLIED RESPIRATORS (NIOSH
APPROVED) IS RECOMMENDED
Ventilation:LOCAL, FLOOR FANS IN AREAS WHERE FLUORINE LEAKS ARE POSS
Protective Gloves:NEOPRENE/RUBBER
Eye Protection:SAFETY GLASSES/FACESHIELD
Other Protective Equipment:BOOTS (NEOPRENE OR BUTYL RUBBER), EYEWASH &
SHOWER.
Supplemental Safety and Health
MSDS DATE: 07/80. MOLECULAR WEIGHT: 38.00

=====
Physical/Chemical Properties
=====

H

CC:G4

Boiling Pt:B.P. Text:-188C

Vapor Density:1.31

Spec Gravity:1.14

Evaporation Rate & Reference:(ETHER = 1)