View NSN Online: https://aerobasegroup.com/nsn/8010-00-935-7077

AMERON INDUSTRIAL COATINGS DIVISION -- 794-702 -- 8010-00-935-7077

Product ID:794-702 MSDS Date:01/01/1987

FSC:8010

NIIN:00-935-7077

MSDS Number: BFXWF === Responsible Party ===

Company Name: AMERON INDUSTRIAL COATINGS DIVISION

Emergency Phone Num:316-733-1361

CAGE:09869

=== Contractor Identification ===

Company Name: AMERON INDUSTRIAL COATINGS DIVISION

Address:20 1 N BERRY ST Box:City:BREA State:CA

ZIP:92621-3904 Country:US

Phone:714-529-4597

CAGE:09869

======= Composition/Information on Ingredients ========

Ingred Name: ISOPROPYL ALCOHOL (SARA III)

CAS:67-63-0

RTECS #:NT8050000 Fraction by Wt: 4.1%

OSHA PEĹ:400 PPM/500 STEL ACGIH TLV:400 PPM/500STEL;9192

Ingred Name: METHYL ETHYL KETONE (2-BUTANONE) (MEK) (SARA III)

CAS:78-93-3

RTECS #:EL6475000 Fraction by Wt: 27.2%

OSHA PEL:200 PPM/300 STEL ACGIH TLV:200 PPM/300STEL 9192

EPA Rpt Qty:50

00 LBS DOT Rpt Qty:5000 LBS

Ingred Name: TOLUENE (SARA III)

CAS:108-88-3

RTECS #:XS5250000 Fraction by Wt: 12.9%

OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name: CYCLOHEXANONE (SARA III)

CAS:108-94-1

RTECS #:GW1050000 Fraction by Wt: 23.8% OSHA PEL:S, 50 PPM

ACGIH TLV:S, 25 PPM; 9293

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

========== Hazards Identification ================

Effects of Overexposure:INHALE:ANESTHETIC,IRR ITATION OF RESPIRATORY

TRACT.ACUTE NERVOUS SYSTEM DEPRESSION CHARACTERIZED BY

First Aid:INCASE OF CONTACT, FLUSH SKIN AND EYES WITH PLENTY OF WATER WHILE REMOVING CONTAMINATED CLOTHING.IF INHALED, REMOVE TO FRESH AIR.CALL A PHYSICIAN IF SYMPTOMS PERSIST

============= Fire Fighting Measures ========================

Flash Point: 45F,7C TCC

Lower Limits: 1.0

Extinguishing Media: CARBON DIOXIDE/DRY CHEMICAL-SMALL;

POLYMER

FOAM-LARGE FIRE

Fire Fighting Procedures: SELF-CONTAINED BREATHING APPARATUS AVAILABLE FOR FIREMEN

Unusual Fire/Explosion Hazard: CLOSED CONTAINERS EXPOSED TO HEAT MAY EXPLODE DUE TO PRESSURE BUILD UP

======== Accidental Release Measures ============

Spill Release Procedures: REMOVE ALL SOURCES OF IGNITION (FLAMES, HOT SURFACES, AND ELECTRICAL, STATIC, OR FRICTIONAL SPARKS) AVOID BREATHING VAPORS. VENTILATE AREA. REMOVE WITH INERT ABSORBENT AND NON-SPARKING

TOOLS.
============= Handling and Storage =============
Handling and Storage Precautions:DO NOT STORE ABOVE 120F.STORE LARGE QUANTITIES IN BUILDINGS DESIGNED AND PROTECTED FOR STORAGE OF NFPA CLASS ONE FLAMMABLE (OR COMBUSTIBLE)LIQUID Other Precautions:DO NOT TAKE INTERNALLY,CONTAINERS SHOULD BE GROUNDED WHEN POURING,AVOID FREE FALL IN EXCESS OF A FEW INCHES,DO NOT FLAME CUT,BRAZE,OR WELD COATED MATERIAL WITHOUT VENTILATION
====== Exposure Control
s/Personal Protection ========
Respiratory Protection: APPROVED BUREAU OF MINES RESPIRATORS W/PROPER FILTER OR HOOD
Ventilation:GENERAL DILUTION/LOCAL EXHAUST FOR TLV&LEL SAFETY&WELDING Protective Gloves:ALOT OF CONTACT
Eye Protection:USE EYEWEAR IF SPLASHING
Other Protective Equipment:PREVENT PROLONGED SKIN CONTACT TO CONTAMINATED CLOTHING
Supplemental Safety and Health
BP 79-153C. EFFTS. OF OVEREXPOSURE-HEADACHE, DIZZINESS ETC OR COMA.PRIMARY IRRITATION FOR SKIN OR EYE CONTACT
========== Physical/Chemical Properties ==========
HCC:F3 Boiling Pt:B.P. Text:174-308F Evaporation Rate & Description Reference: