

THREE BOND OF AMERICA,INC. -- TB1361D(C) -- 8030-00-964-7537

=====
Product Identification
=====

Product ID:TB1361D(C)

MSDS Date:01/01/1987

FSC:8030

NIIN:00-964-7537

MSDS Number: BFZMQ

=== Responsible Party ===

Company Name:THREE BOND OF AMERICA,INC.

Emergency Phone Num:213-556-3614

CAGE:60859

=== Contractor Identification ===

Company Name:THREE BOND OF AMERICA,INC.

Address:20815 HIGGINS COURT

Box

:City:TORRANCE

State:CA

ZIP:90501

Country:US

Phone:310-320-3342

CAGE:60859

=====
Composition/Information on Ingredients
=====

Ingred Name:DIMETHACRYLATE ESTERS

Fraction by Wt: 55.0%

Ingred Name:PLASTICIZER

Fraction by Wt: 32.0%

Ingred Name:TERTIARY AMINE

Fraction by Wt: 1.0%

Ingred Name:CATALYST

Fraction by Wt: 1.0%

=====
Hazards Identification
=====

Effects of Overexposure:EYE/SKIN IRRITATION.POTENITAL SKIN SENSITIZER.

=====

===== First Aid Measures =====

First Aid:SKIN:FLUSH WITH WATER. EYES:FLUSH WITH WATER FOR 15 MIN. CALL DR. WASH SOILED CLOTHES BEFORE REUSE. DISCARD CONTAMINATED SHOES.

===== Fire Fighting Measures =====

Flash Point:>200F,93C CC

Extinguishing Media:FOAM,CO*2 OR DRY CHEM.,WATERSPRAY

Fire Fighting Procedures:COOL ALL CONTAINERS NOT IGNITED WITH FIRE HOSES.

Unusual Fire/Explosion Hazard:RAPID POLYMERIZATION MAY OCCUR AT HIGH TEM

P. SMOKE MAY CONTAN MONOMER-IRRITATE LUNGS.

===== Accidental Release Measures =====

Spill Release Procedures:AVOID EYE AND SKIN CONTACT,OR ORAL INGESTION.WEAR PROTECTIVE CLOTHING.WASH AREA WELL AND COLLECT MATERIAL FOR INCINERATION

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN A COOL PLACE OUT OF DIRECT SUNLIGHT.CHANGE OF CLOTHING SHOULD BE AVAILABLE.AT END OF SHIFT WORKER SHOULD SHOWE

R TO REMOVE VAPORS FROM PORES

Other Precautions:FIRE FIGHTERS MUST WEAR SELF-CONTAINED AIR SUPPLY.SHOES SHOULD BE AIRED OUT DAILY.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NO SPECIAL VENITLATION REQUIRED

Ventilation:OOCAL EXHAUST,NORMAL VENTILATION ADEQUATE

Protective Gloves:IMPERVIOUS

Eye Protection:CHEM.SAFETY GOGGLES

Other Protective Equipment:IMPERVIOUS OVERSHOES AND PROTECTIVE CLOTHING

Supplemental Safety and Health

=====

Physical/Chemical Properties =====

HCC:N1

Boiling Pt:B.P. Text:>6000F

Evaporation Rate & Reference:< ETHER

Appearance and Odor:BLUE LIQUID

Percent Volatiles by Volume:0.5

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:NO

PEROXIDES,STRONG OXIDIZING AGENTS,IRON RUST,STRONG BASES

Stability Condition to Avoid:>90F,EXPOSURE TO LIGHT,OPEN FLAME,METAL CONTACT,VACUUM

Hazardous Decomposition Products:CO AND CO*2

=====

===== Disposal Considerations =====

Waste Disposal Methods:CHEM.INCINERTOR.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.