

OLIN HUNT SPECIALTY PRODUCT,INC -- SAVIN COPIER TONER (870/880) -- 6850-01-026-7239

=====  
Product Identification  
=====

Product ID:SAVIN COPIER TONER (870/880)

MSDS Date:01/01/1987

FSC:6850

NIIN:01-026-7239

Kit Part:Y

MSDS Number: BGFQN

=== Responsible Party ===

Company Name:OLIN HUNT SPECIALTY PRODUCT,INC

City:PALISADES PARK

State:NJ

ZIP:07650

Info Phone Num:201-944-4000

Emergency Phone Num:201-9

44-4000

CAGE:OLINH

=== Contractor Identification ===

Company Name:FUJI HUNT PHOTOGRAPHIC CHEMICALS INC

Address:W 115 CENTURY RD

Box:988

City:PARAMUS

State:NJ

ZIP:07653-0988

Country:US

Phone:201-967-9603

CAGE:73877

Company Name:OLIN HUNT SPECIALTY PRODUCTS INC.

Address:5 GARRET MOUNTAIN PLAZA

City:WEST PATERSON

State:NJ

ZIP:07424

Country:US

Phone:203-789-5436

CAGE:OLINH

=====  
Composition/Information on Ingredients  
=====

Ingred Name:CARBON BLACK

CAS:1333-86-4

RTECS #:FF5800000

Fraction by Wt: 01.3%  
OSHA PEL:3.5 MG/M3  
ACGIH TLV:3.5 MG/M3; 9192

Ingred Name:MIXED ISODECANES  
Fraction by Wt: 92.0%  
ACGIH TLV:300PPM(PER MFR)

Ingred Name:INERT MATERIALS(PIGMENTED RESINOUS MATERIALS)  
Fraction by Wt: 06.7%

=====  
Hazards Identification  
=====

Effects of Overexposure:INHAL:HEAD,NAUSEA,MILD DEPRSSION/RESP  
IRRIT;INGEST:UPSET STOMACH;POSS IRRIT/NAUSEA;SKIN/EYES:IRRIT

=====  
First Aid Measures  
=====

First  
Aid:INHAL:RMV TO FRESH AIR. IF NOT BRTHNG GIVE CPR; IF BRTHNG  
DIFF GIVE OXYGEN. EYE:IMMED FLUSH W/PLENTY OF WATER. SKIN:WASH  
W/SOAP & WATER. RMV CONTAM CLTHG & SHOES. INGEST:DO NOT INDUCE  
VOMIT. NOTHG BY MOUTH IF UNCONSC. GET MEDICAL ATTN.

=====  
Fire Fighting Measures  
=====

Flash Point:125-128F TCC  
Lower Limits:0.7%  
Upper Limits:6.5%  
Extinguishing Media:FOAM-TYPE EXTINGUISHERS-SUPERIOR TO CO\*2  
EXTINGUISHER  
Fire Fighting Procedures:NO WATER ON  
MATL. WATER SPRAY TO ABSORB  
VAPOR/COOL CONT.  
Unusual Fire/Explosion Hazard:SOME OF MATL MAY BURN. CONT MAY EXPLODE  
IN HEAT OF FIRE.

=====  
Accidental Release Measures  
=====

Spill Release Procedures:USE PROTCTV EQUIP.ELIM IGNITION  
SOURCES.PROVIDE VENTILATION;SMALL SPILL(