View NSN Online: https://aerobasegroup.kr/nsn/6850-01-264-0835

MAGNAFLUX CORPORATION -- ZE-3 ZYGLO EMULSIFIER -- 6850-01-264-0835

Product ID:ZE-3 ZYGLO EMULSIFIER

MSDS Date:06/22/1989

FSC:6850

NIIN:01-264-0835

Kit Part:Y

MSDS Number: BGRTF === Responsible Party ===

Company Name: MAGNAFLUX CORPORATION

Address:7300 W LAWRENCE AVE

City:CHICAGO

State:IL

ZIP:60656-3504

Country:US

Info Phone Num:708-867-8000 Emergency Phone Num:708

-867-8000

Preparer's Name: BRUCE C. GRAHAM, CH. CHEM

CAGE:37676

=== Contractor Identification ===

Company Name: ILLINOIS TOOL WORKS INC MAGNAFLUX DIV

Address:3624 WEST LAKE AVENUE

Box:City:GLENVIEW

State:IL ZIP:60025 Country:US

Phone:847-657-5300/

CAGE:37676

======= Composition/Information on Ingredients ========

Ingred Name: MINERAL OIL (EXPOSURE REGULATED AS 'OIL MIST')

CAS:8012-95-1

RTECS #:PY8030000 Fraction by Wt: 50.0% OSHA PEL:5 MG/M3

ACGIH TLV:5 MG/M3/10 STEL;9192

Ingred Nam

Fraction by Wt: 50% Other REC Limits:NONE ESTABLISHED
======================================
Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Effects of Overexposure:INHALATION: NOT LISTED BY MANUFACTURER; HOWEVER,FINE SPRAY/MIST MAY IRRITATE BREATHING PASSAGES; EYES: LIQUID/MIST CAUSES IRRITATION; SKIN: PROLONGED OR REPEATED CONTACT CAUSES IRRITATION BY DISSOLVIN G SKIN OILS; INGESTION: CAUSES GASTRIC UPSET. Medical Cond Aggravated by Exposure:NONE SPECIFIED BY THE MANUFACTURER.
======================================
First Aid:INHALATION: REMOVE TO FRESH AIR; SKIN: REMOVE CONTAMINATED CLOTHES.WASH OFF PROMPTLY WITH SOAP & WATER.USE SOOTHING LOTION.GE MEDICAL HELP IF IRRITATION PERSISTS; EYES: IMMEDIATELY RINSE EYES WITH CO PIOUS AMOUNT OF WATER.GET MEDICAL ASSISTANCE IF IRRIT ION PERSISTS; INGESTION: DO NOT INDUCE VOMITING. GET MEDICAL ATTENTION IF INGESTED.
======================================
Flash Point Method:PMCC Flash Point:325F/163C Extinguishing Media:CARBON DIOXIDE,FOAM Fire Fighting Procedures:KEEP CONTAINERS COOL WITH WATER SPRAY. Unusual Fire/Explosion Hazard:WHEN INVOLVE IN COMBUSTION,MAY EMIT TOXIC GASES AT OR ABOVE DECOMPOSITION TEMPERATURE.
========= Accidental Release Measures ==========
Spill Release Procedures:RE MOVE IGNITION SOURCES.SMALL SPILL:WIPE UP OR MOP UP BUT DO NOT BREATHE VAPORS.PLACE RAGS IN CLOSED DRUMS; LARGE SPILL: WEAR PERSONAL SAFETY EQUIPMENTS.DIKE AREA FAR AHEAD.ABSORB LIQUID WITH COMMERCI AL ABSORBENT.TRANSFER WASTE MATL IN SALVAGE TANKS.
=========== Handling and Storage ============
Handling and Storage Precautions:STORE AWAY FROM HEAT SOURCES IN WELL VENTILATED AREA.AVOID AGAINST PHYSICAL DAMAGE TO CONTAINERS.KEEP

e:"NOT HAZARDOUS" INGREDIENTS

CONTAINERS TIGHTLY CL

OSED. Other Precautions:DO NOT BREATHE VAPORS.DO NOT SMOKE WHILE USING.DO NOT HEAT ABOVE 130F(54C).AVOID FREQUENT OR PROLONGED SKIN CONTACT.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:USE NIOSH APPROVED RESPIRATOR FOR CONFINED AREAS. Ventilation:GENERAL ROOM VENTILATION TO KEEP BELOW TLV LIMIT. Protective Gloves:USE NITRILE RUBBER GLOVES IF NEEDED. Eye Protection:FULL GOGGLES/SAFETY GLASSES W/SIDESHIELD Other Protective Equipment:NOT KNOW N Work Hygienic Practices:WASH OFF PROMPTLY WITH WATER.AVOID SKIN CONTACT.
Supplemental Safety and Health NSN IS FOR A 2 PARTS SET OF MIL-I-25135E. I/A/W QPL-25135-15,THE SET OF TYPE I,METHOD B,LEVEL 3 MAY CONSIST OF ZL-1D PENETRANT, AND ZE-3 OR ZE-4B EMULSIFIER. THIS ENTRY DESCRIBES ZE-3. SEE OTHER PN IN D FOR EMULSIFIERS. ALSO SEE QPL & SPEC FOR MORE DETAILS. KEY1:N1.
======================================
HCC:N1 Boiling Pt:B.P. Text:>450F/>232C Vapor Pres:0.3 @100F Vapor Density:>1.0 Spec Gravity:0.945 pH:8.0 Solubility in Water:NEGLIGIBLE Appearance and Odor:VISCOUS PINK LIQUID
========= Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES NONE STATED BY MANUFACTURER. Stability Condition to Avoid:HEAT,HIGH TEMPERATURES. Hazardous Decomposition Products:EMITS OXIDES OF CARBON IF BURNING.
========= Disposal Considerations =============

Waste Disposal Methods:INCINER

ATE OR DISPOSE OF AS EPA HAZARDOUS WASTE

D001 (IGNITABLE WASTE), IN ACCORDANCE WITH ALL APPLICABLE
FEDERAL, STATE, LOCAL REGULATIONS; IF LOCAL AUTHORITIES PROHIBIT
DUMPING RINSINGS DOWN THE SEWER, PURIFY RINSINGS WITH MAGNAFLUX
WASTEWATER TREATMENT

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warra nts this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.