View NSN Online: https://aerobasegroup.com/nsn/6850-01-266-4550

MAGNAFLUX CORPORATION -- ZL-30B ZYGLO PENETRANT -- 6850-01-266-4550

Product ID:ZL-30B ZYGLO PENETRANT

MSDS Date:11/19/1986

FSC:6850

NIIN:01-266-4550

MSDS Number: BGRYK === Responsible Party ===

Company Name: MAGNAFLUX CORPORATION

Address:7300 W. LAWRENCE AVENUE

City:CHICAGO

State:IL ZIP:60656 Country:US

Info Phone Num:312-867-8000

Emergency Phone Num:312-867-8000

Preparer's Name: BRUCE C. GRAHAM

CAGE:37676

=== Contractor Identification ===

Company Name: ILLINOIS TOOL WORKS INC MAGNAFLUX DIV

Address:3624 WEST LAKE AVENUE

Box:City:GLENVIEW

State:IL ZIP:60025 Country:US

Phone:847-657-5300/

CAGE:37676

====== Composition/Information on Ingredients ========

Ingred Name:DISTILATES(PETROLEUM), CATALYTIC REFORMER FRACTIONER

RESIDUE, LOW BOILING

CAS:68477-31-6 Fraction by Wt: 30.0%

Ingred Name: KEROSENE

CAS:8008-20-6

RTECS #:OA5500000

Fraction by

Wt: 05.0%

ACGIH TLV:100MG/CUM

Ingred Name:LUBRICATING OIL(PETROLEUM),CLAY TREATED (MINERAL OIL-CLAY

TREATED) CAS:64742-50-3

Fraction by Wt: 100.0%

========== Hazards Identification ================

Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO Health Hazards Acute and Chronic:IRRITATES EYES.

Effects of Overexposure:INHALATION:CAUSES DIZZINESS,DROWSINESS,NAUSEA; SKIN:LIQUID IRRITATES BY DISSOLVING SKIN OIL; EYES:VAPORS/LIQUID CAUSES IRRITATION.

Medical Con

d Aggravated by Exposure: NOT KNOWN.

First Aid:INHALATION:REMOVE TO FRESH AIR.IF BREATHING IS DIFFICULT, GIVE OXYGEN; SKIN:REMOVE CONTAMINATED CLOTHES.WASH OFF WITH FLOWING WATER.USE SOOTHING LOTION.IF IRRITATION PERSISTS, GET MEDICAL ATTN; EYES:IMM EDIATELY RINSE/FLUSH WITH COPIOUS AMOUNTS OF RUNNING WATER, AND GET MEDICAL ATTENTION.

=========== Fire Fighting Measures ==============

Flash Poi

nt Method:PMCC

Flash Point:>200F/>93C

Extinguishing Media: CARBON DIOXIDE, FOAM.

Fire Fighting Procedures: KEEP CONTAINERS COOL WITH WATER SPRAY.

Unusual Fire/Explosion Hazard:WHEN INVOLVE IN COMBUSTION,MAY EMIT TOXIC GASES AT OR ABOVE DECOMPOSITION TEMPERATURE.

========= Accidental Release Measures ============

Spill Release Procedures:REMOVE IGNITION SOURCES.SM QTY:WIPE UP OR MOP UP BUT DO NOT BREATHE VAPORS.PLACE RAGS IN CLOSED DRUMS; LG QTY:WEAR PERSONAL SAFETY EQ

LIQUID WITH COMMERCIAL ABSORBEN T.TRANSFER WASTE MATL IN SALVAGE TANKS.
=========== Handling and Storage =============
Handling and Storage Precautions:STORE AWAY FROM HEAT SOURCES IN WELL VENTILATED AREA.AVOID AGAINST PHYSICAL DAMAGE TO CONTAINERS.KEEP CONTAINERS TIGHTLY CLOSED. Other Precautions:DO NOT BREATHE VAPORS.DO NOT SMOKE WHILE USING.DO NOT HEAT ABOVE 130F(54C).AVOID FREQUENT OR PROLONGED SKIN CONTACT.
==== Exposure Controls/Personal Protection =======
Respiratory Protection:WEAR A RESPIRATOR WITH COMMERCIAL CARTRIDGE. IN CONFINED AREAS,WEAR A FULL MASK WITH SEPARATE AIR SUPPLY. Ventilation:GENERAL VENTILATION TO KEEP BELOW 350PPM LIMIT. Protective Gloves:NITRILE RUBBER GLOVES. Eye Protection:FULL GOGGLES.
Other Protective Equipment: EITHER USE IN A SPRAY BOOTH OR NEXT TO AN
EXHAUST VENT. Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING.LAUNDER CONTAMINATED CLOTH ES BEFORE RE-USE.
Supplemental Safety and Health ITEM IS A 2 PARTS KIT.UNDER MIL-I-25135,TYPE I,METHOD D,LEVEL 4,THE KIT/NSN MAY CONSIST OF ZL-30B OR ZL-37 PENETRANT AND AN EMULSIFIER(QPL-25135-15 SPECIFIED EITHER ZR-10A OR ZR-10B EMULSIFIER BE USED WITH THE ABOVE PENETRANT);KEY1:N1;THISENTRY DESCRIBES ZL-30B PENETRANT;SEE PNI C & D,THIS NSN,FOR EMULSIFIER DATA.
========= Physical/Chemical Properties ==========
HCC:N1 Boiling Pt:B.P. Text:410F/210C Vapor Pres:1.0 Spec Gravity:0.96 Solubility in Water:NEGLIGIBLE Appearance and Odor:GREEN LIQUID. Percent Volatiles by Volume:5%
========= Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES NONE KNOWN. Stability Condition to Avoid:HEAT,HIGH TEMPERATURES. Hazardous Decomposition Products:EMITS OXIDES OF CARBON AND NITROGEN ON COMBUSTION.
======= Disposal Considerations ==========
Waste Disposal Methods:INCINERATE OR DISP

UIPMENTS.DIKE AREA FAR AHEAD.ABSORB

OSE OF AS EPA HAZARDOUS WASTE
D001 (IGNITABLE WASTE), IN ACCORDANCE WITH ALL APPLICABLE
FEDERAL, STATE, LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek compet ent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.