View NSN Online: https://aerobasegroup.kr/nsn/7930-01-301-5249

PPG INDUSTRIES INC CHEMICAL DIVISION -- DX440:DITZ-O WAX & GREASE REMOVER --7930-01-301-5249

Product ID:DX440:DITZ-O WAX & GREASE REMOVER MSDS Date:06/09/1986 FSC:7930 NIIN:01-301-5249 MSDS Number: BHHKT === Responsible Party === Company Name: PPG INDUSTRIES INC CHEMICAL DIVISION Address: ONE GATEWAY CENTER City:PITTSBURGH State:PA ZIP:15222-1416 Country:US Info P hone Num:412-434-3131 OR 412-963-5822 Emergency Phone Num:304-843-1300 CAGE:93915 === Contractor Identification === Company Name: PPG INDUSTRIES INC CHEMICAL DIVISION Address: ONE GATEWAY CENTER City:PITTSBURGH State:PA ZIP:15222-1416 Country:US Phone:304-843-1300 CAGE:93915 Ingred Name:NAPHTHA, MEDIUM ALIPHATIC CAS:64742-88-7 Fraction by Wt: 35.0%

Ingred Name:XYLENES (O-,M-,P- ISOMERS) (SARA III) CAS:1330-20-7 RTECS #:ZE2100 000 Fraction by Wt: 65.0% OSHA PEL:100 PPM/150 STEL ACGIH TLV:100 PPM/150STEL;9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Routes of Entry: Inhalation: YES Skin: YES Ingestion: YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ACUTE:IRRITATION OF EYES, SKIN, RESPIRATORY OR G.I. TRACTS; CNS EFFECTS LIKE HEADACHE, DIZZINESS, NAUSEA, VOMITING AND POSSIBLE UNCONSCIOUSNESS; REDNESS OR B **URNS OF EYES/SKIN** POSSIBLE.CHRONIC:DRYING OF SKIN, D EFATTING OR DERMATITIS, CNS DAMAGE Explanation of Carcinogenicity:DATA PER MSDS Effects of Overexposure: SEE HEALTH HAZARDS DATA. Medical Cond Aggravated by Exposure: PERSONS WITH A HISTORY OF AILMENTS OR WITH A PRE-EXISTING DISEASE INVOLVING THE EYES, SKIN, OR RESPIRATORY TRACT MAY BE AT INCREASED RISK FROM EXPOSURE. First Aid:INHALATION:REMOVE TO FRESH AIR. RESUSC ITATE IF NOT BREATHING. GET MEDICAL ATTENTION. EYES: IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR 15 MINUTES HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. SKIN:REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP AND WATER. IF IRRITATION PERSISTS, GET MEDICAL ADVICE. INGESTION:DO NOT INDUCE VOMITING. GIVE NOTHING BY MOUTH IF UNCONSCIOUS. GET IMMEDIATE MEDICAL ATTENTION. Flash Point Method: PMCC Flash Point:77.0F, 25.0C Lower Limits:1.0 Extinguishing Media: USE CARBON DIOXIDE, FOAM, DRY CHEMICAL, OR WATER FOG. Fire Fighting Procedures: FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard: FIRE OR EXCESSIVE HEAT MAY CAUSE PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS.

Spill Release Proced

ures: USE PROPER PERSONAL PROTECTION; CONTAIN FREE MATERIAL IF POSSIBLE; USE SUITABLE INERT ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL IN AN APPROVED CONTAINER. Neutralizing Agent:NOT APPLICABLE. Handling and Storage Precautions: STORE IN A COOL, DRY, WELL VENTILATED AREA, KEEP CONTAINERS TIGHTLY CLOSED WHEN NOT IN USE, PROTECT CONTAINERS FROM PHYSICAL DAMAGE. Other Precautions: DO NOT TAKE INTERNALLY. DO NO T BREATHE MIST. AVOID PROLONGED OR REPEATED BREATHING OF VAPOR. AVOID CONTACT WITH EYES. USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING. Respiratory Protection: USE NIOSH/MSHA APPROVED RESPIRATOR FOR ORGANIC VAPORS/MIST AS REQUIRED IF ABOVE PEL/TLV OR SCBA IN AN ENCLOSED AREA. Ventilation:LOCAL/GENERAL TO MAINTAIN PEL/TLV. Protective Gloves: NEOPRENE, NITRILE, OR NATURAL RUBBER **Eve Protection:SAFET** Y GOGGLES WITH OPTIONAL FACE SHIELD Other Protective Equipment: EYE WASH STATION AND SAFETY SHOWER, WORK CLOTHING AND APRON AS REQUIRED. Work Hygienic Practices: OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR FOOTWEAR. Supplemental Safety and Health AVOID PROLONGED OR REPEATED EXPOSURE. DO NOT GET ON SKIN OR IN EYES. DO NOT BREATHE VAPORS OR MISTS. HCC:F2 Boiling Pt:B.P. Text:352F,178C Vapor Pres:5.0MMHG Vapor Density:>1.0 Spec Gravity:0.83 Evaporation Rate & amp; Reference:47(N-BUTYL ACETATE = 1) Solubility in Water:NEGLIGIBLE Appearance and Odor: FLAMMABLE LIQUID Percent Volatiles by Volume:100.0

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS,STRONG MINERAL ACIDS AND ALKALIES. Stability Condition to Avoid:HIGH TEMPERATURES, SPARKS, AND OPEN FLAMES Hazardous

Decomposition Products: CARBON MONOXIDE, CARBON DIOXIDE AND OTHER UNIDENTIFIED COMPONENTS.

Waste Disposal Methods:CONSULT LOCAL AUTHORITIES.DISPOSAL MUST BE MADE IN ACCORDANCE WITH ALL APPLICABLE FEDERAL, STATE AND LOCAL LAWS AND REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States o

f America in no manner whatsoever,

expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.