View NSN Online: https://aerobasegroup.kr/nsn/6850-01-263-7247

ARDROX INC -- 985-P14 FLUORESCENT DYE PENETRANT -- 6850-01-263-7247

Product ID:985-P14 FLUORESCENT DYE PENETRANT

MSDS Date:02/01/1990

FSC:6850

NIIN:01-263-7247

MSDS Number: BJDQS === Responsible Party === Company Name:ARDROX INC Address:16961 KNOTT AVE

City:LA MIRADA

State:CA

ZIP:90638-6015 Country:US

Info Phone Num:714-739-2821

Emergency Phone Num:800-424-9300

P

reparer's Name: SHEREE L. KINZEL

CAGE:23373

=== Contractor Identification ===

Company Name: BRENT AMERICA, INC.

Address:16961 KNOTT AVE.

Box:City:LA MIRADA

State:CA

ZIP:90638-6015

Country:US

Phone:714-739-2821

CAGE:23373

======= Composition/Information on Ingredients ========

Ingred Name: WHITE MINERAL OIL

CAS:8042-47-5

RTECS #:PY8047000

Other REC Limits: NONE SPECIFIED

Ingred Name: MINERAL OIL

CAS:64742-65-0 RTECS #:PY8038500

Other REC Limits:5 MG/M3

Ingred Name: AROMATIC NAPHTA

CAS

| :64741-68-0 | | | |
|-------------|------------|---------------|-----|
| Other REC L | imits:NONE | SPECIF | IED |

========= Hazards Identification ============================

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ACUTE:IRRITATION OF

EYES, SKIN, RESPIRATORY OR G.I. TRACTS; CNS EFFECTS LIKE
HEADACHE, DIZZINESS, NAUSEA AND VOMITING. REDNESS OR BURNS OF

EYES/SKIN POSSIBLE.CHRONIC:DRYING OF SKIN, DEFATTING OR DERMATITIS.

Explanation of Carcinogenicity

:DATA PER MSDS

Effects of Overexposure:MAY CAUSE IRRITATION OF EYES,SKIN,RESPIRATORY OR G.I.TRACTS;MAY CAUSE HEADACHE,DIZZINESS,NAUSEA,VOMITING OR GI TRACT DISTURBANCES POSSIBLE.BURNS OR REDNESS OF EYES/CRACKING OR DRYNESS OF SKIN.

Medical Cond Aggravated by Exposure:PERSONS WITH A HISTORY OF AILMENTS OR WITH A PRE-EXISTING DISEASE INVOLVING THE EYES, SKIN, OR RESPIRATORY TRACT MAY BE AT INCREASED RISK FROM EXPOSURE.

| ======================================= | First Aid Measures | ========= |
|---|--------------------|-----------|
| ======= | | |

First Aid:INHALATION:REMOVE TO FRESH AIR. RESUSCITATE IF NOT BREATHING. GET MEDICAL ATTENTION. EYES:IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR 15 MINUTES HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. SKIN:REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP AND WATER. IF IRRITATION PERSISTS, GET MEDICAL ADVICE. INGESTION:DO NOT INDUCE VOMITING. GIVE NOTHING BY MOUTH IF UNCONSCIOUS. GET IMMEDIATE MEDICAL ATTENTION.

| | Fire Fighting Measures | ===== |
|---|------------------------|-------|
| ======================================= | | |

Flash Point Method:PMCC Flash Point:>200F,>93C

Autoignition Temp: Autoignition Temp Text: 428F

Lower Limits:1.1 Upper Limits:6.0

Extinguishing Media: USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL.

Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE.

Unusual Fire/Explosion Hazard: SLIGHT FIRE HAZARDS

====== Accidental R

| elease Measures ========== |
|---|
| Spill Release Procedures:USE PROPER PERSONAL PROTECTION;CONTAIN FREE MATERIAL IF POSSIBLE;USE SUITABLE INERT ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL IN AN APPROVED CONTAINER. Neutralizing Agent:NOT APPLICABLE. |
| ============ Handling and Storage ============= |
| Handling and Storage Precautions:STORE IN A COOL, DRY, WELL VENTILATED AREA. KEEP CONTAINERS TIGHTLY CLOSED WHEN NOT IN USE. PROTECT CONTAINERS FROM PHYSICA L DAMAGE. |
| Other Precautions:DO NOT TAKE INTERNALLY. DO NOT BREATHE MIST. AVOID PROLONGED OR REPEATED BREATHING OF VAPOR. AVOID CONTACT WITH EYES. USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING. |
| ====== Exposure Controls/Personal Protection ======== |
| Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR AS REQUIRED IF ABOVE PEL/TLV OR SCBA IN AN ENCLOSED AREA. Ventilation:LOCAL/GENERAL TO MAINTAIN PEL/TLV. Protective Gloves:NEOPRENE, NITRILE, OR NATURA |
| L RUBBER |
| Eye Protection:SAFETY GOGGLES WITH OPTIONAL FACE SHIELD Other Protective Equipment:EYE WASH STATION AND SAFETY SHOWER,WORK CLOTHING AND APRON AS REQUIRED. |
| Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR FOOTWEAR. |
| Supplemental Safety and Health AVOID PROLONGED OR REPEATED EXPOSURE. DO NOT GET ON SKIN OR IN EYES. DO NOT BREATHE VAPORS OR MISTS. |
| |

| ========== Physical/Chemical Properties |
|---|
| |

HCC:N1 Boiling Pt:B.P. Text:>200F,>93C Vapor Pres: