View NSN Online: https://aerobasegroup.com/nsn/8030-00-227-1698

## FLAMEMASTER CORP / CHEM SEAL DIV -- CS 2725 PART B -- 8030-00-227-1698

Product ID:CS 2725 PART B

MSDS Date:09/05/1990

FSC:8030

NIIN:00-227-1698

Kit Part:Y

MSDS Number: BNPMQ === Responsible Party ===

Company Name: FLAMEMASTER CORP / CHEM SEAL DIV

Address:11120 SHERMAN WAY

City:SUN VALLEY

State:CA ZIP:91352 Country:US

Info Phone Num:818-982-1650

**Emergency Phon** 

e Num:800-424-9300(CHEMTREC) Preparer's Name:HERBERT H. MOORE

CAGE:14439

=== Contractor Identification ===

Company Name: FLAMEMASTER CORP THE CHEM SEAL DIV

Address:11120 SHERMAN WAY

Box: City: SUN VALLEY

State:CA

ZIP:91352-4949 Country:US

Phone:818-982-1650

CAGE:14439

======= Composition/Information on Ingredients ========

Ingred Name:TRIETHYLENE PENTAMINE

CAS:112-57-2

RTECS #:KH8585000 Fraction by Wt: 5%

Other REC Limits:5 PPM SKIN

===== Hazards Identification ===

\_\_\_\_\_ Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: VAPOR/MIST CAN IRRITATE THE NOSE AND THROAT. SEVERELY IRRITATING TO EYES AND SKIN. MATERIAL CAN CAUSE SKIN SENSITIZATION AND DERMATITIS. Effects of Overexposure: HEADACHE, DIZZINESS, TEARING OF EYES AND NOSE IRRITATION. ITCHING OF SKIN WITH SIGN OF REDNESS. Medical Cond Aggravated by Exposure: ASTHMA, LIVER. ============ ====== First Aid Measures ============ First Aid:EYE AND SKIN CONTACT: FLUSH EYES WITH WATER FOR AT LEAST 15 MINUTES. CONSULT PHYSICIAN, WASH SKIN WITH SOAP AND WATER. ============ Fire Fighting Measures ========================= Flash Point Method:TCC Flash Point:>200F,>93C Extinguishing Media: FOAM, CO2, DRY CHEMICAL, WATER SPRAY. Fire Fighting Procedures: IN CONFINED AREAS WEAR SELF-CONTAINED BREATHING APPARATUS. Unusual Fire/Explosion Hazard: OXIDES OF NITROGEN, MAY BE PRODUCTS OF COMBUSTION. ========= Accidental Release Measures ============

Spill Release Procedures: SCOOP UP AND RETURN TO CONTAINER. WASH AREA WITH SOAP AND WATER.

Neutralizing Agent: ACIDS.

============= Handling and Storage ==========================

Handling and Storage Precautions: STORE IN COOL DRY AREAS AWAY FROM DIRECT SUN LIGHT. KEEP IN CLOSED CONTAINERS.

Other Precautions: AVOID CONTACT WITH SKIN, EYES AND CLOTHING. WASH CONTAMINATED CLOTH

ING BEFORE RE-USE.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:NIOSH APPROVED RESPIRATOR WITH ORGANIC VAPOR CANISTER.  Ventilation:LOCAL, GENERAL: FAN.  Protective Gloves:RUBBER.  Eye Protection:SAFETY GLASSES.  Other Protective Equipment:APRON AND SAFETY SHOES.  Work Hygienic Practices:DO NOT SMOKE, DRINK OR EAT IN WORK AREAS.  Supplemental Safety and Health KEY1:C4.
========= Physical/Chemical Properties ===========
HCC:B3 Boil ing Pt:B.P. Text:550 F Melt/Freeze Pt:M.P/F.P Text: