View NSN Online: https://aerobasegroup.kr/nsn/3680-01-230-1947

Product ID:STEINEX - ALL GRADES MSDS Date:04/30/1992 FSC:3680 NIIN:01-230-1947 MSDS Number: BPBPZ === Responsible Party === Company Name: APPLIED INDUSTRIAL MATERIALS CORP Address: ONE PARKWAY NORTH, SUITE 400 City:DEERFIELD State:IL ZIP:60015 Country:US Info Phone Num:708-632-9065 Emerge ncy Phone Num:708-940-8700 CAGE:0BEY7 === Contractor Identification === Company Name: APPLIED INDUSTRIAL MATERIALS CORP Address: ONE PARKWAY NORTH, SUITE 400 Box:City:DEERFIELD State:IL ZIP:60015 Country:US Phone:708-940-8700 CAGE:0BEY7 Ingred Name:SODIUM SILICATE CAS:1344-09-8 Fraction by Wt: >50%

Ingred Name:WATER CAS:7732-18-5 RTECS #:ZC0110000

Routes of

Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: INHALATION: DUSTS ARE IRRITATIONG TO MUCOUS MEMBRANES OF THE RESPIRATORY TRACT, MOUTH, THROAT, ESOPHAGUS & STOMACH. EYES/SKIN: IRRITATION. Explanation of Carcinogenicity:NONE Effects of Overexposure: SHORT TERM: MAY CAUSE IRRITATION TO SKIN, EYES, NOSE AND THROAT; GASTROINTESTINAL TRACT UPSET. LONG TERM: LONG TERM EXPOSURE MAY CAUSE IRRITATION AND R EDNESS OF SKIN. AND EYES **IRRITATION.** Medical Cond Aggravated by Exposure: THERE IS NO KNOWN MEDICAL CONDITIONS ABNORMALLY AGGRAVATED BY EXPOSURE THIS PRODUCT. First Aid: EYES: FLUSH WWITH LARGE AMOUNTS OF WATER FOR AT LEAST SEVERAL MINUTES. SEEK MED ATTN. SKIN: WASH WITH PLENTY OF WATER FOR AT LEAST 15 MINUTES. WASH AND REMOVE SOILED CLOTHING & FOOTWEAR BEFORE REUSE. SEEK MED ATTN. INHALATION: IF SYMPTOMS A **RE PRESENT GET** PERSON OUT OF AREA TO FRESH AIR. SEEK MED ATTN. Flash Point:NONE Extinguishing Media:CO2, DRY CHEMICAL, WATER FOG Fire Fighting Procedures: THIS PRODUCT IS NON-COMBUSTIBLE. USE WATER TO COOL EXPOSED CONTAINERS. Unusual Fire/Explosion Hazard:NONE Spill Release Procedures: IF A MATERIAL IS SPILLED OR RELEASED, STEPS SHOULD BE TAKE TO CONTAIN LIQUIDS/PREVENT DISCHARGES TO STREAMS OR SEWER SYSTEMS. COVER WITH SODA ASH, REMOVE INTO A CONTAINER, MIX AND ADD WATER TO DILUTE. NEUTRALIZE WITH ACID. MAY BE DRAINED W/PLENTY WTR Neutralizing Agent: SODIUM CARBONATE AND DILUTE ACETIC ACID. Handling and Storage Precautions: STORE IN A COOL, DRY LOCATION. PROTECT FROM FREEZING.

Other Precautions:NONE

======= Exposure Controls/Personal Protection

Respiratory Protection:USE A NIOSH/MSHA APPROVED RESPIRATOR FOLLOWING MANUFACTURER'S RECOMMENDATIONS WHERE MISTS OR SPRAY MAY BE GENERATED.
Ventilation:PROVIDE LOCAL EXHAUST VENITLATION WHERE MISTS OR SPRAY MAY BE GENERATED, IF ENGINEERING CONTROLS ARE NOT FEASIBLE.
Protective Gloves:RUBBER
Eye Protection:FACE SHIELD, CHEMICAL GOGGLES
Other Protective Equipment:STANDARD WORK CLOTHING/SHOES. SHOWER & EYEWASH FACILITIES.
Work Hygienic Practices:REMOVE/WASH CONTAMINA
TED CLOTHING/FOOTWEAR BEFORE REUSE.
Supplemental Safety and Health WT PER GAL: 12.0-13.0 LBS.

HCC:N1 Vapor Density:>AIR Spec Gravity:1.5 pH: