View NSN Online: https://aerobasegroup.kr/nsn/6665-01-011-4269

Product ID:3464-2 MSDS Date:10/22/1992 FSC:5895 NIIN:01-011-4269 **MSDS Number: BPCBL** === Responsible Party === Company Name: WING CORP Address:215 HIGHLAND AVE City:WESTMONT State:NJ ZIP:08108-2613 Country:US Info Phone Num:609-854-2225 Emergency Phone Num:609-854-2225 Preparer's Name: HMIS TECHNICIAN CAGE:97536 === Contractor Identification === Company Name: WING CORP Address:215 HIGHLAND AVE. City:WESTMONT State:NJ ZIP:08108-2613 Country:US Phone:609-854-2225 CAGE:97536 Ingred Name: AMERICIUM 241 Fraction by Wt: 100% Other REC Limits:NONE SPECIFIED 

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and

Chronic:AMERICIUM IS A HIGHLY RADIOTOXIC SUBSTANCE WITH A LONG HALF LIFE. HOWEVER IT IS HIGHLY UNLIKELY THAT ANY SERIOUS HEALTH PROBLEMS WOULD DEVELOP FROM USE IN THIS DEVICE DUE TO THE SMALL AMOUNT OF MATERI AL IN THE DEVICE. IF LARGE AMOUNTS ARE INHALED OR INGESTED A CANCER COULD RESULT. Explanation of Carcinogenicity:WHILE NOT LISTED, AMERICIUM IS RADIOACTIVE; RADIOACTIVES HAVE BEEN KNOWN TO CAUSE CANCER. Effects of Overexposure:SOME SIGNS OF RADIATION SICKNESS ARE: HAIRLO SS, HEMORRHAGING OF BLOOD VESSELS IN SKIN, NAUSEA, VOMITING, CHANGES IN BLOOD, WEAKNESS.
======================================
First Aid:INHALED: REMOVE TO FRESH AIR. SEE DOCTOR. EYES: FLUSH WITH WATER FOR 15 MINUTES WHILE HOLDING EYELIDS OPEN. SEE DOCTOR. SKIN: REMOVE COMTAMINATED CLOTHES. WASH WITH SOAP AND WATER. SEE DOCTOR. INGESTE D: GET IMMEDIATE MEDICAL ATTENTION.
======================================
Ex tinguishing Media:MEDIA APPROPRIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE CLOTHING. Unusual Fire/Explosion Hazard:CONTAINS RADIOACTIVE MATERIAL.
Spill Release Procedures:ISOLATE AREA AND DENY ENTRY. NOTIFY RADIATION/SAFETY AUTHORITIES. WEAR PROPER PROTECTIVE EQUIPMENT/CLOTHING. SWEEP UP, MOP AREA. PLACE ALL MATERIALS IN CONTAINER FOR LATER DIS PSOAL.
======================================
Handling and Storage Precautions:PROTECT FROM PHYSICAL DAMAGE. Other Precautions:NONE
======================================
Respiratory Protection: NONE NORMALLY REQUIRED. IF A LARGE NUMBER OF

DEVICES ARE DAMAGED, USE NIOSH/MSHA APPROVED RESPIRATOR WITH HEPA CARTRIDGE. IF INVOLVED IN FIRE, USE SCBA. IF RESPIRATORY PROTECTION USED; A PROGRAM IAW 2 9 CFR 1910.134 MUST BE IMPLEMEN TED.
Ventilation:NONE NORMALLY REQUIRED.
Protective Gloves:SPILL-RUBBER
Eye Protection:SPILL-SAFETY GLASSES
Other Protective Equipment:SPILL-COVERALLS OR DISPOSABLE GARMETS TO
PROVIDE MAXIMUM BODY COVERAGE TO PREVENT SKIN CONTACT WITH SPILLED
MATERIAL.
Work Hygienic Practices:WASH HANDS AFTER HANDLING OR BEFORE EATING,
DRINKING, OR SMOKING.
Supplemental Safety and Health
MSDS GENERATED BY HMIS TECHNICIAN FOR TECHNICAL SUPPORT. MANUFACTURER

DOES NOT PROVIDE MSDS' FOR ITS SMOKE DET

ECTORS AND SIMILAR DEVICES.

THIS MSDS IS OBSOLETE; CURRENT NSN IS 6665-01011-4269.

HCC:A2 Boiling Pt:B.P. Text:2607F,1431C Melt/Freeze Pt:M.P/F.P Text:994F,534C Spec Gravity:13.67 Solubility in Water:NEGLIGIBLE Appearance and Odor:AMERICIUM IS CONTAINED IN DEVICE: SILVERY METAL, NO ODOR.

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, ST ATE AND

FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this inform ation to their particular situation.