

BF GOODRICH THE ADHESIVE PRODUCTS DIV -- MA562 -- 8040-00-185-5631

=====  
Product Identification  
=====

Product ID:MA562

MSDS Date:09/29/1992

FSC:8040

NIIN:00-185-5631

MSDS Number: BQYBT

=== Responsible Party ===

Company Name:BF GOODRICH THE ADHESIVE PRODUCTS DIV

Address:123 WEST BARTGES STREET

City:AKRON

State:OH

ZIP:44311-1081

Country:US

Info Phone Num:216-374-2900

Emergency Phone Num:216-374-282

4

Preparer's Name:CLIFFORD PEARSON

CAGE:1HS43

=== Contractor Identification ===

Company Name:SIA ADHESIVES INC

Address:123 W BARTGES ST

Box:City:AKRON

State:OH

ZIP:44311-1081

Country:US

Phone:330-374-2786 / 330-374-2900

CAGE:1HS43

=====  
Composition/Information on Ingredients  
=====

Ingred Name:OXYBIS (BENZEN-SULFONYL)

CAS:80-51-3

RTECS #:DB7321000

Fraction by Wt: 3%

Other REC Limits:NONE SPECIFIED

Ingred Name:BISPHENOL A EPICHLORO HYDREN SYSTEM

Fraction by Wt: 59%

Other REC L

imits:NONE SPECIFIED

Ingred Name:POLYAMIDE SYSTEM  
Fraction by Wt: 4%  
Other REC Limits:NONE SPECIFIED

Ingred Name:VOC: NONE  
RTECS #:9999999VO  
Other REC Limits:NONE SPECIFIED

=====  
===== Hazards Identification =====

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:SKIN: REDNESS OF SKIN, MINOR  
IRRITATION. SOME PEOPLE DEVELOP ALLERGIC REACTION AND  
SENSITIZATION.

Explanation of Carcinogenicity:NONE KNOWN  
Effects of Overexpos  
ure:EYES: MAY CAUSE MINOR TRANSIENT IRRITATION  
Medical Cond Aggravated by Exposure:SKIN RASHES

=====  
===== First Aid Measures =====

First Aid:SKIN CONTACT: WASH WITH SOAP AND WATER. SEE A PHYSICIAN IF  
IRRITATION DEVELOPS. EYE CONTACT: FLUSH WITH WATER FOR 15 MINUTES.  
SEE A PHYSICIAN.

=====  
===== Fire Fighting Measures =====

Extinguishing Media:WATER FOG, CARBON DIOXIDE, DRY CHEMICAL, FOAM  
Fire Fighting Procedures:DO NOT ENTE  
R CONFINED FIRE SPACE WITHOUT  
PROPER PROTECTIVE EQUIPMENT INCLUDING NIOSH APPROVED SELF BREATHING  
APPARATUS.  
Unusual Fire/Explosion Hazard:NONE KNOWN - TOXIC FUMES POSSIBLE

=====  
===== Accidental Release Measures =====

Spill Release Procedures:AVOID EYE AND SKIN CONTACT. PICK UP AND PLACE  
IN CONTAINER FOR DISPOSAL.

=====  
===== Handling and Storage =====

Handling and Storage Precautions:STORE AT 0F OR LESS IN A DRY PLACE.  
AVOI

D EYE AND SKIN CONTACT.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NOT USUALLY NECESSARY UNDER MOST CONDITIONS OF USE.

Ventilation:GOOD GENERAL VENTILTION AT POINT OF CURE.

Protective Gloves:CLOTH

Eye Protection:GOGGLES

Other Protective Equipment:CLEAN LONG SLEEVE AND LONG LEG CLOTHING.

Supplemental Safety and Health

=====  
===== Physical/Chemical Properties =====

HCC:N1

Decomp Temp:Decomp Text:>300F,>149C

Spec Gravity:

1.22

Viscosity:SOLID

Solubility in Water:NIL

Appearance and Odor:YELLOW, SOLID, EPOXY ODOR

Percent Volatiles by Volume:0.0

=====  
===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

ACTIVE AMINE COMPOUNDS IN UNCONTROLLED CONDITIONS.

Stability Condition to Avoid:AREAS OF HEAT

Hazardous Decomposition Products:CARBON DIOXIDE, CARBON MONOXIDE, AMMONIA AND OTHER TOXIC FUMES POSSIBLE.

Conditions to Avoid Polymerization:HEATING MATERIAL IN LARGE MASSES

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particula

r situation.