

TBA INDUSTRIAL PRODUCTS -- TBA 510 -- 5330-01-194-8989

=====  
===== Product Identification =====

Product ID:TBA 510  
MSDS Date:11/10/1987  
FSC:5330  
NIIN:01-194-8989  
MSDS Number: BTGJJ  
=== Responsible Party ===  
Company Name:TBA INDUSTRIAL PRODUCTS  
Box:40  
City:ROCHDALE, LANCS  
Country:EN  
Info Phone Num:800-527-1935  
Emergency Phone Num:800-527-1935  
CAGE:01309

==== Contractor Identification ====

Company Name:R-WA  
Y GASKET AND SUPPLY CO  
Address:1950 E SEDGLEY AVE  
Box:City:PHILADELPHIA  
State:PA  
ZIP:19124-5622  
Country:US  
Phone:215-697-6350/215-743-1650  
CAGE:5S153  
Company Name:TBA INDUSTRIAL PRODUCTS  
Box:40  
City:ROCHDALE, LANCS  
Country:EN  
Phone:800-527-1935  
CAGE:01309

=====  
===== Composition/Information on Ingredients =====

Ingred Name:ASBESTOS, CHRYSOTILE (SARA III)  
CAS:12001-29-5  
RTECS #:CI6478500  
Fraction by Wt: 72%  
Other REC Limits:NONE RECOMME  
OSHA PEL:0.2 FIBERS/CC  
ACGIH TLV:2 FIBERS/CC

; A1;9394

Ingred Name:INERT FILLERS  
Fraction by Wt: 3%  
Other REC Limits:NONE RECOMME

Ingred Name:SYNTHETIC RUBBER  
Fraction by Wt: 20%  
Other REC Limits:NONE RECOMME

Ingred Name:CURING AGENTS  
Fraction by Wt: 5%  
Other REC Limits:NONE RECOMME

=====  
===== Hazards Identification =====

LD50 LC50 Mixture:TLV ASBESTOS=0.2 FIBERS/CC  
Routes of Entry: Inhalation:YES Skin:NO Ingestion:YES  
Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES  
Health Hazards Acute and Chronic:HEALTH HAZARD-HAZARD WOULD ARISE ONLY  
IF PRODUCT IS SUBJECTED TO MECHANICAL ACTION THAT WOULD RELEASE  
FIBERS.ACUTE HAZARD:EYE AND SKIN IRRITATION. CHRONIC  
HAZARD:INHALATION OF AIRBORNE FIBERS CAN CAUSE ASBESTOSIS,LUNG  
CANCER AND MESOTHELIOMA.INGESTION CAN CAUSE CANCER OF GI TRACT AND  
LARYNX.  
Explanation of Carcinogenicity:ASBESTOS IS LISTED UNDER NTP,IARC AND  
OSHA.  
Effects of Overexposure:EYE/SKIN:IRRITATION. INHALATION:LABORED  
BREATHING,RESTRICTED PULMONARY FUNCTION.  
Medical Cond Aggravated by Exposure:INDIVIDUALS WITH A HISTORY OF SKIN  
AND RESPIRATORY DISORDERS MAY BE AT INCREASED RISK FROM EXPOSURE.  
HIGHER RISK WITH SMOKERS.

=====  
===== First Aid Measures =====

First Aid:EYES:FLUSH WITH PLENTY OF WATER FOR AT LEAST 15 MINUTES.IF  
IRRITATION PERSISTS,SEE DOCTOR. SKIN:WASH WITH SOAP AND WATER WHILE  
REMOVING CONTAMINATED CLOTHING AND SHOES.IF IRRITATION PERSISTS,SEE  
DOCTOR. INHALATION:REMOVE VICTIM

TO FRESH AIR.SEE DOCTOR.

INGESTION:NO SPECIFIC ACTION.SEE DOCTOR.

=====  
===== Fire Fighting Measures =====

Flash Point:NONE

Extinguishing Media:USE WATER OR FOAM.

Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH WATER SPRAY.

Unusual Fire/Explosion Hazard:FIRE CONDITIONS MAY CREATE TOXIC FUMES FROM THE RUBBER COMPONENT.

=====  
===== Accidental Release Measures =====

Spill Release Procedures:USE WET COLLECTION METHOD.VACUUM UP WITH HEPA FILTERED VACUUM CLEANER. WEAR PROTECTIVE EQUIPMENT AND HALF FACE RESPIRATOR WITH HEPA FILTERS.

Neutralizing Agent:NOT APPLICABLE.

=====  
===== Handling and Storage =====

Handling and Storage Precautions:STORE IN CLEAN,DRY PLACE,AWAY FROM STRONG OXIDIZING AGENTS. NORMAL WASH UP AFTER HANDLING IS RECOMMENDED.

Other Precautions:ASBESTOS IS BOUNDED BY AN ELASTOMETER COMPOUND, HOWEVER, DO NOT MISUSE BY IMPROPER CUTTING OR HANDLING.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE NORMALLY REQUIRED. IF FIBERS MAY BE RELEASED, USE NIOSH APPROVED HALF FACE RESPIRATOR WITH HEPA FILTER FOR ASBESTOS FIBERS.

Ventilation:NO SPECIAL REQUIREMENT UNDER NORMAL CONDITIONS. IF FIBERS MAY BE RELEASED, USE LOCAL EXHAUST VENTILATION.

Protective Gloves:NOT NORMALLY REQUIRED.

Eye Protection:SAFETY GLASSES.

Other Protective Equipment:USE FULL BODY PROTECTION IF THE PEL IS EXCEEDED.

Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING AND BEFORE EATING. LAUNDRY CONTAMINATED CLOTHING BEFORE REUSE.

Supplemental Safety and Health

AS MANUFACTURED, LOCKED-IN ASBESTOS DOES NOT PRESENT A HAZARD. ONLY WHEN THE ITEM IS SUBJECTED TO ABRASIVE ACTIONS AND DUST IS GENERATED, THEN ASBESTOS FIBERS MAY BE RELEASED AND BECOME AIRBORNE.

=====  
===== Physical/Chemical Properties =====

rties =====

HCC:T6

Solubility in Water:INSOLUBLE

Appearance and Odor:SHEET;BLACK;SLIGHT RUBBERY ODOR.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZING AGENTS

Stability Condition to Avoid:HIGH HEAT, OPEN FLAMES AND OTHER SOURCES  
OF IGNITION

Hazardous Decomposition Products:SMOKE,CARBON MONOXIDE,ASBESTOS  
FIBERS,UNKNOWN PRODUCTS.

===== Disposal Considerations =====

=

Waste Disposal Methods:CONTACT YOUR LOCAL ENVIRONMENTAL OFFICER.

ASBESTOS DUST SHOULD BE WETTED AND VACUUMED UP WITH HEPA FILTERED  
VACUUM CLEANER,SEALED IN A PLASTIC BAG,AND TURNED IN TO DISPOSAL  
COMPANY.DISPOSE OF IN ACCORDANCE WITH ALL LAWS AND REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or  
implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.