

JET-LUBE INC -- WLD

MSDS Safety Information

FSC: 9150  
NIIN: 01-179-0228  
MSDS Date: 08/11/1993  
MSDS Num: BVVCX  
Product ID: WLD  
MFN: 01  
Responsible Party  
Cage: 07431  
Name: JET-LUBE INC  
Address: 4849 HOMESTEAD RD  
Box: 21258  
City: HOUSTON TX 77226  
Info Phone Number:  
713-674-7617  
Emergency Phone Number: 713-674-7617/800-424-9300(CHEMTREC)  
Preparer's Name: DONALD A. OLDIGES  
Proprietary Ind: Y  
Review Ind: Y  
Published: Y

Contractor Summary

Cage: 07431  
Name: JET-LUBE INC  
Address: 4849 HOMESTEAD RD  
Box: 21258  
City: HOUSTON TX 77026  
Phone: 713-674-7617

Item Description Information

Item Manager: S9G  
Item Name: GREASE,WIRE ROPE-EXPOSED GEAR  
Specification Number: NONE  
Type/Grade/Class: NONE  
Unit of Issue: CN  
Quantitative Expression: 00000000035LB  
UI Container Qty: 0  
Type of Container: CAN

Ingredients

Name: \*\*\* PROPRIETARY \*\*\*

Health Hazard

## s Data

=====

LD50 LC50 Mixture: TLV FOR OIL MIST IS 5 MG/M3.

Route Of Entry Inds - Inhalation: NO

Skin: NO

Ingestion: NO

Carcinogenicity Inds - NTP: NO

IARC: NO

OSHA: NO

Effects of Exposure: TARGET ORGANS:EYES, SKIN, RESPIRATORY TRACT. ACUTE-  
PROLONGED EYE/SKIN CONTACT WILL CAUSE IRRITATION. PROLONGED INHALATION OF  
VAPORS/OIL MIST WILL CAUSE LUNG IRRITATION & MAY BE HARMFUL. MAY BE  
HARMFUL/FATAL IF INGESTED. CHRONIC- UNKNOWN.

Explanat

ion Of Carcinogenicity: NONE

Signs And Symptoms Of Overexposure: EYES, SKIN, RESPIRATORY TRACT IRRITATION

Medical Cond Aggravated By Exposure: HEART PROBLEMS IN HIGH VAPOR CONCENTRATION

First Aid: GET MEDICAL ATTENTION IF SYMPTOMS PERSIST. SKIN:REMOVE BY  
WIPING/WATERLESS HAND CLEANER FOLLOWED BY WASHING SKIN WITH SOAP & WATER.  
EYE:FLUSH WITH WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. INHALED:REMOVE TO  
FRESH AIR & PROVIDE OXYGEN/CPRIF NEEDED. ORAL:DO NOT INDUCE VOMITING.  
CALL P  
HYSICIAN.

=====

Handling and Disposal

=====

Spill Release Procedures: SCOOP UP EXCESS GREASE, WIPE UP WITH RAGS, PICK-UP  
RESIDUE WITH NON-FLAMMABLE ABSORBENT MATERIAL SUCH AS DIATOMACEOUS EARTH,  
SAND OR VERMICULITE. SWEEP UP AND TRANSFER TO A CONTAINER FOR PROPER DISPOS  
AL. CLEAN AREA WITH APPROPRIATE CLEANER.

Neutralizing Agent: NOT RELEVANT

Waste Disposal Methods: CONSULT LOCAL, STATE AND  
FEDERAL REGULATIONS FOR

PETROLEUM PRODUCTS AND CHLORINATED SOLVENTS DISPOSAL.

Handling And Storage Precautions: STORE AWAY FROM HEAT, STRONG OXIDIZING AGENTS  
AND DIRECT SUNLIGHT.

Other Precautions: USE ONLY IN WELL VENTILATED AREAS. AVOID PROLONGED/REPEATED  
BREATHING OF FUMES/MISTS. AVOID CONTACT WITH EYES AND SKIN. DO NOT TAKE  
INTERNALLY. WASH THOROUGHLY AFTER USING. KEEP OUT OF REACH OF CHILDREN.

=====

Fire and Explosion Hazard Informa

tion  
=====

Flash Point Method: COC  
Flash Point Text: >430F,>221C  
Autoignition Temp Text: 500F  
Lower Limits: >0.9  
Upper Limits: >7.0  
Extinguishing Media: USE CARBON DIOXIDE, FOAM, SAND/EARTH OR DRY CHEMICAL.  
WATER MAY CAUSE FROTHING.  
Fire Fighting Procedures: WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL  
FACED SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH  
WATER SPRAY.  
Unusual Fire/Explosion Hazard: N  
ONE

=====

Control Measures

=====

Respiratory Protection: USE ONLY IN WELL VENTILATED AREA. IF EXCESSIVE MISTING  
PRESENT, USE NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS.  
Ventilation: LOCAL EXHAUST  
Protective Gloves: POLY VINYL ALCOHOL  
Eye Protection: SAFETY GLASSES  
Other Protective Equipment: EYE WASH STATION & SAFETY SHOWER  
Work Hygienic Practices: OBSERVE GOOD PERSONAL HYGIENE PRACTICES  
AND  
RECOMMENDED PROCEDURES. WASH HANDS BEFORE EATING.

=====

Physical/Chemical Properties

=====

HCC: T6  
NRC/State LIC No: NOT RELEVANT  
B.P. Text: >165F,>74C  
M.P/F.P Text: UNKNOWN  
Decomp Text: UNKNOWN  
Vapor Pres: <100  
Vapor Density: >1  
Spec Gravity: 1.10  
Viscosity: UNKNOWN  
Solubility in Water: NIL  
Appearance and Odor: BLACK SEMI-FLUID WITH CHARACTERISTIC SOLVENT ODOR  
Percent Volatile

s by Volume: 15 MAX  
Corrosion Rate: UNKNOWN

Reactivity Data

Stability Indicator: YES  
Stability Condition To Avoid: EXCESSIVE HEAT, FLAMES  
Materials To Avoid: STRONG OXIDIZING AGENTS  
Hazardous Decomposition Products: CARBON MONOXIDE, CARBON DIOXIDE, HYDROCHLORIC ACID, CARBONYL CHLORIDE, SULFUR DIOXIDE, OXIDES OF NITROGEN & OTHER GASES  
Hazardous Polymerization Indicator: NO  
Conditions  
To Avoid Polymerization: NOT RELEVANT

Toxicological Information

Ecological Information

MSDS Transport Information

Regulatory Information

Other Information

Transportation Information

Responsible Party Cage: 07431  
Trans ID NO: 113214  
Product ID: WLD  
MSDS Prepared Date: 08/11/1993  
Review Date: 11/30/1994  
MFN: 1  
Net Unit Weight: 35.0 LBS  
Multiple KIT Number: 0  
Review IND: Y  
Unit Of Issue: CN  
Container QTY: 0  
Type Of Container: CAN

Detail DOT Information

DOT PSN Code: ZZZ  
DOT Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION

Detail IMO Information

IMO PSN Code: ZZZ  
IMO Proper

Shipping Name: NOT REGULATED FOR THIS MODE OF TRANSPORTATION

Detail IATA Information

IATA PSN Code: ZZZ

IATA Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION

Detail AFI Information

AFI PSN Code: ZZZ

AFI Proper Shipping Name: NOT REGULATED BY THIS MODE OF T  
RANSPORTATION

HAZCOM Label

Product ID: WLD

Cage: 07431

Company Name: JET-LUBE INC

Street: 4849 HOMESTEAD RD

PO Box: 21258

City: HOUSTON TX

Zipcode: 77026

Health Emergency Phone: 713-674-7617/800-424-9300(CHEMTREC)

Label Required IND: Y

Date Of Label Review: 11/30/1994

Status Code: C

MFG Label NO: UNKNOWN

Label Date: 11/30/1994

Origination Code: F

Eye Protection IND: YES

Skin Protectio

n IND: YES

Signal Word: WARNING

Health Hazard: Moderate

Contact Hazard: Moderate

Fire Hazard: None

Reactivity Hazard: None

Hazard And Precautions: TARGET ORGANS:EYES, SKIN, RESPIRATORY TRACT. ACUTE-  
PROLONGED EYE/SKIN CONTACT WILL CAUSE IRRITATION. PROLONGED INHALATION OF  
VAPORS/OIL MIST WILL CAUSE LUNG IRRITATION & MAY BE HARMFUL. MAY BE  
HARMFU L/FATAL IF INGESTED. CHRONIC- UNKNOWN. STORE AWAY FROM OXIDIZERS &  
SUNLIGHT. PICK-UP SPILL WITH DIATOMACEOUS EARTH. CLEAN AREA WITH CLEA

NER.

FIRST AID- GET MEDICAL ATTENTION IF SYMPTOMS PERSIST. SKIN: REMOVE BY WIPING/WATERLESS HAND CLEANER FOLLOWED BY WASHING SKIN WITH SOAP & WATER. EYE:FLUSH WITH WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. INHALED:REMOVE TO FRESH AIR & PROVIDE OXYGEN/CPR IF NEEDED. ORAL:DO NOT INDUCE VOMITING. CALL PHYSICIAN.

=====

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense.

The United States of America in no manner whatsoever expressly or implied warrants, states, or intends said information to have any application, use or viability by or to any person or persons outside the Department of Defense nor any person or persons contracting with any instrumentality of the United States of America and disclaims all liability for such use. Any person utilizing this instruction who is not a military or civilian employee of the

United States of America should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation regardless of similarity to a corresponding Department of Defense or other government situation.