View NSN Online: https://aerobasegroup.kr/nsn/8030-00-881-5238

Product ID:WS-516A ACCELERATOR

MSDS Date:08/01/1994

FSC:8030

NIIN:00-881-5238

Kit Part:Y

MSDS Number: BXDNW === Responsible Party ===

Company Name: J AND R INDUSTRIES (FACTORY LOCATION)

Address:800 E. ANAHEIM ST

City:WILMINGTON

State:CA ZIP:90744 Country:US

Info Phone Num:310-476-71

21

Emergency Phone Num:310-476-7121

CAGE:7X230

=== Contractor Identification ===

Company Name: J AND R INDUSTRIES (FACTORY LOCATION)

Address:800 E. ANAHEIM ST

Box:City:WILMINGTON

State:CA ZIP:90744 Country:US

Phone:310-476-7121

CAGE:7X230

Company Name: TECHCON SYSTEMS INC

Address:1059 E BEDMAR ST

Box:City:CARSON

State:CA

ZIP:90746-3601 Country:US CAGE:22975

======= Composition/Information on Ingredients ========

Ingred Name:LEAD OXIDE

CAS:1309-60-0

RTECS #:OG0700000

Fraction by Wt:

70%
Other REC Limits:NONE SPECIFIED
======================================
Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:N/A. MFR GAVE NO OTHER INFORMATION ON
MSDS.
Explanation of Carcinogenicity:MANUFACTURER GAVE NO INFORMATION ABOUT
CARCINOGENICITY. HMIS DOES NOT EXPECT IT TO BE CARCINOGENIC.
Effects of Overexposure:MFR GAVE NO INFORMATION ON MSDS.
Medical Cond
Aggravated by Exposure:MFR GAVE NO INFORMATION ON MSDS.
======================================
First Aid:USE PLENTY OF WATER. MFR GAVE NO FURTHER INFORMATION ON MSDS. (HMIS:ALSO SEE OTHER PRECAUTIONS.)
======================================
Flash Point:400F,204C
Extinguishing Media:STANDARD COMMERCIAL EXTINGUISHER
Fire Fighting Procedures:STANDARD
Unusual Fire/Explosion Hazard:NONE
======== Accidental Release Measur
es ===========
Spill Release Procedures:WASH WITH PLENTY OF WATER.
Neutralizing Agent:MFR GAVE NO INFORMATION ON MSDS.
======================================

Handling and Storage Precautions: CONTAINS TOXIC LEAD COMPOUND. AVOID CONTACT WITH SKIN AND INGESTION. ALWAYS WASH HANDS BEFORE EATING & SMOKING.

Other Precautions:IF ACCELERATOR CONTACTS SKIN FLUSH AREA WITH WARM WATER. IN CASE OF INGESTION OBTAIN MEDICAL ATTENTION. STORE IN CLOSED CON

ly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.