

OEA AEROSPACE INC. -- 51325-3 TRANSFER CONNECTOR -- 1377-01-241-7982

===== Product Identification =====

Product ID:51325-3 TRANSFER CONNECTOR

MSDS Date:01/12/1996

FSC:1377

NIIN:01-241-7982

MSDS Number: CCGLS

=== Responsible Party ===

Company Name:OEA AEROSPACE INC.

Address:HWY 12 AND ET RD

Box:KK

City:FAIRFIELD

State:CA

ZIP:94533-0659

Country:US

Info Phone Num:707-422-1880

Emergency Phone Num:707-

422-1880

Preparer's Name:S SCHOOLFIELD/J KOHRING

CAGE:17610

=== Contractor Identification ===

Company Name:OEA AEROSPACE INC

Address:3530 BRANSCOMBE RD

Box:KK

City:FAIRFIELD

State:CA

ZIP:94533-0659

Country:US

Phone:707-422-1880

CAGE:17610

===== Composition/Information on Ingredients =====

Ingred Name:HEXANITROSTILBENE I

Ingred Name:HEXANITROSTILBENE II

===== Hazards Identification =====

Routes of Entry: Inhalation:NO Skin:NO Ingestion:YES

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:HEXANITROTILBENE I & II IS POSITIVE  
BIOLOGICAL ACTIVITY IN THE AMES MUTAGENICITY TEST. INHALATION:  
IRRITATION TO NOSE, THROAT, MUCOUS MEMBRANES, NAUSEA & ALLERGIC  
REACTIONS. SKIN: IRRITATION, ALLERGIC REACTIONS. EYES: IRRITATION.  
INGESTION: TOXIC.  
Explanation of Carcinogenicity:NONE  
Effects of Overexposure:IRRITATION, NAUSEA, REDNESS.

===== First Aid Measures =====  
=====

First Aid:EYES: FLUSH W/WATER FOR 15 MINS. SKIN: WASH W/SOAP & WATER.  
INHALATION: REMOVE TO FRESH AIR. OBTAIN MEDICAL ATTENTION IN ALL  
CASES.

===== Fire Fighting Measures =====

Extinguishing Media:DON'T ATTEMPT TO EXTINGUISH.  
Fire Fighting Procedures:EVACUATE AREA. USE SCBA W/FULL FACE.  
Unusual Fire/Explosion Hazard:IF EXPOSED TO FIRE, UNIT MAY  
ACTUATE/EXPLODE.

===== Accidental Release Measures =====

Spill  
Release Procedures:CALL LOCAL HAZARDOUS MATERIALS TEAM. REMOVE  
IGNITION SOURCES. COVER/EXPOSE MATERIAL W/VEGETABLE OIL & REMOVE  
FOR APPROVED DISPOSAL. USE FLAME RETARDANT CLOTHING, SAFETY GLASSES  
& NON-SPARKING TOOLS.

===== Handling and Storage =====

Handling and Storage Precautions:DON'T STORE AT TEMP >200F. ANTI-STATIC  
BAGS SHALL BE USED FOR STORAGE & SHIPPING.

===== Exposure Controls/Personal Protection =====

Respiratory

Protection:WEAR NIOSH APPROVED HEPA RESPIRATOR IF PEL/TLV  
ARE EXCEEDED.  
Ventilation:LOCAL EXHAUST: REQUIRED FOR TEST FIRING.  
Protective Gloves:POLY-BENZ-IMMIEAZOLE  
Eye Protection:SAFETY GLASSES  
Other Protective Equipment:FLAME RETARDANT COAT & GROUNDING STRAPS TO  
PREVENT ELECTROSTATIC DISCHARGE.  
Supplemental Safety and Health

===== Physical/Chemical Properties =====

Solubility in Water:LOW/SLIGHT  
Appearance and Odor:YELLOW POWDER W/NO ODOR.

=====

== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES  
ALKALIS, COPPER, BRONZE, CORROSIVES & OXIDIZERS.  
Stability Condition to Avoid:MECHANICAL SHOCK, STATIC ELECTRICITY,  
HEAT, FLAME/SPARKS.  
Hazardous Decomposition Products:CO, NITROGEN, NITROUS OXIDES,  
HYDROGEN, CARBON, CO2, WATER.

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IAW/FEDERAL, STATE & LOCAL  
REGULATIONS. UNFIRED UNITS/WAST  
E, DISPOSE AS REACTIVE HAZARDOUS  
WASTE, D003.

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.