View NSN Online: https://aerobasegroup.kr/nsn/6685-00-477-2170

PRAXAIR INC -- ARGON IN THERMOMETER -- 6685-00-477-2170

Product ID:ARGON IN THERMOMETER

MSDS Date:12/01/1992

FSC:6685

NIIN:00-477-2170

MSDS Number: CFYMC
=== Responsible Party ===
Company Name:PRAXAIR INC
Address:39 OLD RIDGEBURY RD

City:DANBURY

State:CT

ZIP:06817-0001 Country:US

Info Phone Num:203-794-5782

Emergency Phone Num:203-794-5782

CAGE:0LV01 === Contract

or Identification ===

Company Name: MOELLER INSTRUMENT CO

Address:126 MAIN ST

Box:668

City:IVORYTON

State:CT ZIP:06442 Country:US

Phone:860-767-2104

CAGE:76526

Company Name:PRAXAIR, INC. Address:39 OLD RIDGEBURY RD

Box:City:DANBURY

State:CT

ZIP:06810-5113 Country:US

Phone:800-772-9247; 800-PRAXAIR

CAGE:0LV01

====== Composition/Information on Ingredients ========

Ingred Name: ARGON

CAS:7440-37-1

RTECS #:CF2300000 Fraction by Wt: 100%

Other REC Limits: NONE RECOMMENDED

ACGIH TLV:ASPHY

XIANT; 9596
======================================
LD50 LC50 Mixture:NOT RELEVANT Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:TARGET ORGANS:NONE. ACUTE AND CHRONIC-THEREMOMETER CONTAINS SMALL AMOUNTS OF ARGON. NO HAZARD IS ANTICIPATED IN NORMAL CONDITION OF USE. Explanation of Carcinogenicity:NONE Effects of Overexposure:NONE Medical Cond Aggravated by Exposure: NONE
======================================
First Aid:INHALED:MOVE TO FRESH AIR.
============ Fire Fighting Measures ============
Flash Point:NONE Lower Limits:NOT RELEVANT Upper Limits:NOT RELEVANT Extinguishing Media:USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL FOR SURROUNDING FIRE. Fire Fighting Procedures:WEAR NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS IF NEEDED. Unusual Fire/Explosion Hazard:THERMOMETER MAY RUPTURE DUE TO HEAT OF FIRE.
======== Accidental Release Measures ==========
Spill Release Procedures:VENTILATE AREA. Neutralizing Agent:NOT RELEVANT
============ Handling and Storage =============
Handling and Storage Precautions:HANDLE WITH CARE. KEEP OUT OF REACH OF SMALL CHILDREN. Other Precautions:WASH HANDS AFTER HANDLING.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:NONE SHOULD BE NEEDED. Ventilat

Eye Protection:SAFETY GLASSES RECOMMENDED Other Protective Equipment:NONE SHOULD BE NEEDED. Work Hygienic Practices:OBSERVE GOOD INDUSTRIAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. Supplemental Safety and Health THIS IS A THERMOMETER WHICH HAS SMALL AMOUNTS OF ARGON GAS.
======== Physical/Chemical Properties =========
HCC:G3 NRC/State Lic Num:NOT RELEVANT Boiling Pt:B.P. Text:-303F,-186C Melt/Free ze Pt:M.P/F.P Text:-309F,-189C Vapor Density:1.378 Spec Gravity:GAS Viscosity:NOT RELEVANT Evaporation Rate & Deference:NOT RELEVANT Solubility in Water:NEGLIGIBLE Appearance and Odor:COLORLESS, ODORLESS GAS Percent Volatiles by Volume:100
======== Stability and Reactivity Data ========
Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid:EXCESSIVE HEAT Hazardous Decomposition Products:NONE
======= Disposal Considerations ====================================
Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND

ion:NONE SHOULD BE NEEDED.

Protective Gloves: NONE SHOULD BE NEEDED.

D FEDERAL REGULATIONS

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice t

o verify and assume responsibility for the suitability of this information to their particular situation.