View NSN Online: https://aerobasegroup.com/nsn/5350-00-576-9634

FERRO CORP CATAPHOTE DIV -- GLAS-SHOT, MICROBEADS, MACROBEADS, MICROPERL, GLASS BEADS, -- 5350-00-576-9634

Product ID:GLAS-SHOT, MICROBEADS, MACROBEADS, MICROPERL, GLASS BEADS,

MSDS Date:07/09/1998

FSC:5350

NIIN:00-576-9634 Status Code:A

MSDS Number: CLMTW === Responsible Party ===

Company Name: FERRO CORP CATAPHOTE DIV

Address:1001 UNDERWOOD DR

Box:2369 City:JAC KSON State:MS

ZIP:39205 Country:US

Emergency Phone Num:1-800-221-2574 Preparer's Name:ERNEST CARTER Chemtrec Ind/Phone:(800)424-9300

CAGE:22306

=== Contractor Identification ===
Company Name:CATAPHOTE INC
Address:1001 UNDERWOOD

Box:City:FLOWOOD

State:MI ZIP:39208 Country:US

Phone:601-939-4612

CAGE:0GU70

Company Name: FERRO CORP CATAPHOTE DIV

Address:1001 UNDERWOOD DR

City:JACKSON State:MS ZIP:39205 Country:US

CAGE:22306

Box:2369

====== Composition/Information on Ingredients =======

Ingred Name: NUISANCE DUST OSHA PEL:15 MG/M3 ACGIH TLV:10 MG/M3 Ingred Name: NUISANCE DUST-RESPIRABLE OSHA PEL:5 MG/M3 ACGIH TLV:5 MG/M3 =========== Hazards Identification ========================== Routes of Entry: Inhalation:YES Skin:UNKNOWN Ingestion:YES Effects of Overexposure: MAY CAUSE TEMPORARY RESPIRATORY AND EYE IRRITATION. Medical Cond Aggravated by Exposure: OVEREXPOSURE CAN AGGRAVATE EXISTING RESPIRATORY CONDITIONS AND EYE IRRITATION. ======== Firs t Aid Measures =========== First Aid:IF BEADS OR DUST CAUSE EYE IRRITATION, FLUSH THE EFFECTED EYE(S) WITH WATER OR COMMERCIAL EYE WASH. IF UNABLE TO REMOVE BEAD/DUST BY THIS METHOD, SEEK MEDICAL CARE. IF EXISTING RESPIRATORY CONDITIONS ARE AGGRAVATED IN YOUR USE OF THIS PRODUCT, GET TO A WELL VENTILATED AREA. SEEK MEDICAL ATTENTION IF CONDITION IS NOT ALLEVIATED. ======== Accidental Release Measures ============ Spill Release Procedures:VAC UUM OR SWEEP UP EXCESS MATERIAL TO AVID A POSSIBLE SLIPPING HAZARD. ====== Exposure Controls/Personal Protection ========

Respiratory Protection: USE NIOSH APPROVED DUST RESPIRATOR.

Ventilation: LOCAL EXHAUST: AS REQUIRED FOR NUISANCE DUST MECHANICAL: AS REQUIRED FOR NUISANCE DUST.

Protective Gloves: PROTECTIVE GLOVES: AS REQUIRED PER JOB.

Eye Protection: SAFETY GLASSES/GOGGLES FOR DUST.

Supplemental Safety and Health

======= Physical/Chemical Properties ======

========

Melt/Freeze Pt:=-11.5C, 11.F Spec Gravity:2.4-2.6 G/CM3 Appearance and Odor:WHITE, TASTELESS, ODORLESS.

======== Stability and Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES CONCENTRATED HYDROFLUORIC ACID. Conditions to Avoid Polymerization:WILL NOT OCCUR.

======= Disposal Considerations ============

Waste Disposal Methods:GLASS BEADS ARE CONSIDERED TO BE NON-HAZARDOUS BY THE EPA UNDER 29 CFR 1910.1200, AND IF DI SPOSED AS WASTE, THE

RCRA STATUS OF UNUSED MATERIAL IS NON-HAZARDOUS ACCORDING TO THE LIST OF CERCLA CHEMICAL S. IF PERMITTED BY APPLICABLE FEDERAL, STATE AND LOCAL REGULATION, GLASS BEADS CAN BE DISPOSED OF IN A SOLID WASTE LANDFILL.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.