

IRELAND ALLOYS INC -- STELLITE 30, COBALT BASE ALLOY -- 3439-01-357-7860

=====
Product Identification
=====

Product ID:STELLITE 30, COBALT BASE ALLOY

MSDS Date:11/21/1985

FSC:3439

NIIN:01-357-7860

Status Code:A

MSDS Number: CLPPD

=== Responsible Party ===

Company Name:IRELAND ALLOYS INC

Box:41000

City:HOUSTON

State:TX

ZIP:77240-1000

Country:US

Info Phone Num:713-937-1111

Emergency Phone Num:713-93

7-1111

CAGE:1DWT5

=== Contractor Identification ===

Company Name:IRELAND ALLOYS INC

Box:41000

City:HOUSTON

State:TX

ZIP:77240-1000

Country:US

Phone:713-937-1111

CAGE:1DWT5

=====
Composition/Information on Ingredients
=====

Ingred Name:CHROMIUM

CAS:7440-47-3

RTECS #:GB4200000

= Wt:26.

OSHA PEL:1 MG/M3

ACGIH TLV:0.5 MG/M3

EPA Rpt Qty:1 LB

DOT Rpt Qty:1 LB

Ingred Name:COBALT

CAS:7440-48-4

RTECS #:GF8750000

= Wt:50.

OSHA PEL:0.1 MG/M3

ACGIH TLV:0.05 MG/M3

Ingred Name:IRON

CAS:1

309-37-1
RTECS #:NO7400000
= Wt:2.
OSHA PEL:NONE
ACGIH TLV:NONE

Ingred Name:NICKEL
CAS:7440-02-0
RTECS #:QR5950000
= Wt:15.
OSHA PEL:1 MG/M3
ACGIH TLV:1 MG/M3
EPA Rpt Qty:100 LBS
DOT Rpt Qty:100 LBS

Ingred Name:CARBON
CAS:7440-44-0
RTECS #:FF5250000
= Wt:.45

Ingred Name:MOLYBDENUM
CAS:7439-98-7
RTECS #:QA4680000
= Wt:6.
OSHA PEL:15 MG/M3
ACGIH TLV:10 MG/M3

===== Hazards Identification =====

Reports of Carcinogenicity:NTP:UNKNOWN IARC:YES

Health Hazards Ac

ute and Chronic:SHORT TERM EXPOSURE-METALLIC TASTE;

NAUSEA; TIGHTNESS OF CHEST; FEVER; IRRITATION OF EYES, NOSE, THROAT AND SKIN; LOSS OF CONSCIOUSNESS/DEATH DUE TO WELDING/REMELT GASES OR LACK OF OXYGEN. LONG TERM EXPOSURE- ADVERSE EFFECTS MAY RESULT FROM LONG TIME EXPOSURE TO FUMES, GASES OR DUSTS. THESE EFFECTS MAY INCLUDE SKI SENSITIZATION, NEUROLOGICAL DAMAGE, AND RESPIRATORY DISEASE SUCH AS BRONCHIAL ASTHMA , LUNG FIBROSIS OR PNEUMOCONIOSIS.

Explanation of Carcinog

enicity:NICKEL AND CHROMIUM HAVE BEEN DETERMINED

BY THE IARC TO BE SUSPECTED CARCINOGENS.

Effects of Overexposure:SHORT TERM EXPOSURE-METALLIC TASTE; NAUSEA;

TIGHTNESS OF CHEST; FEVER; IRRITATION OF EYES, NOSE, THROAT AND SKIN; LOSS OF CONSCIOUSNESS/DEATH DUE TO WELDING/REMELT GASES OR LACK OF OXYGEN. LONG TERM EXPOSURE- ADVERSE EFFECTS MAY RESULT FROM LONG TIME EXPOSURE TO FUMES, GASES OR DUSTS. THESE EFFECTS MAY INCLUDE SKI SENSITIZATION, NEUROLOGICAL DAMAGE, AND RESPI

RATORY

DISEASE SUCH AS BRONCHIAL ASTHMA , LUNG FIBROSIS OR PNEUMOCONIOSIS.
Medical Cond Aggravated by Exposure:AGGRAVATION OF PRE-EXISTING
RESPIRATORY OR ALLERGIC CONDITIONS MAY OCCUR IN SOME WORKERS.

=====
First Aid Measures
=====

First Aid:REMOVE VICTIM FROM EXPOSURE AND OBTAIN PROMPT MEDICAL
ATTENTION. IF VICTIM IS UNXONSCIOUS, ADMINISTER OVYGEN, IF NOT
BREATHING, RESUSCIATATE IMMEDIATELY.

=====
Fire Fighting Measures
=====

Flash Point:NON-FLAMMABLE
Fire Fighting Procedures:SOLID FORMS-NON-FLAMMABLE.
Unusual Fire/Explosion Hazard:SHAVINGS OR BORINGS-IN EXTREME CASES, THE
CUTTING OIL CAN IGNITE, BUT THE METAL ITSELF WILL NOT.

=====
Accidental Release Measures
=====

Spill Release Procedures:RESIDUE FROM CUTTING OR GRINDING SHOULD BE
SWEPT OR VACUUMED AND PLACED IN SUITABLE CONTAINERS FOR DISPOSAL BY
LOCAL, STATE OR FEDERAL WASTE DISPOSAL REGULATIONS.

=
=====
Handling and Storage
=====

Other Precautions:PEL/TLV EXPOSURES SHOULD BE KEPT BELOW RECOMMENDED
RECOMMENDATIONS BY OSHA AND ASGIH TO ENSURE PROPER HEALTH
PROTECTION OF WORKER.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:WHEN EXPOSURE LIMITS ARE EXCEEDED, USE PROPER
APPROVED VENTILATOR.
Ventilation:USE LOCAL EXHAUST WHDN CUTTING, GRINDING, WELDING, OR
REMELTING.
Protective Gloves:SHOULD BE US
ED WHEN CUTTING, GRINDING OR WELDING.
Eye Protection:SHOULD BE USED WHEN CUTTING, GRINDING OR WELDING.
Work Hygienic Practices:SHAVINGS OR TURNINGS CONTAINING CUTTING OILS
SHOULD NOT BE ALLOWED TO CONTACT THE SKIN FOR PROLONGED PERIODS.
INADVERTENT SHORT TERM CONTACT IS HARMLESS.
Supplemental Safety and Health
PHYSICAL DATA-COBALT BASE ALLOY PRODUCTS ARE SHIPPED AS SOLID FORMS, OR
AS METAL SHAVINGS OR BOINGS. THE SHAVING OR BORINGS WILL EITHER BE
DRY & COMPLETELY FREE OF CUTTING

OIL, OR WILL CONTAIN A SMALL % OF
WATER SOLUBLE CUTTING OIL. (WHICH IS USED AS A CUTTING TOOL
LUBRICANT WHEN SOLID FORMS ARE MACHINED TO FINAL SIZE).

===== Physical/Chemical Properties =====

HCC:N1
Melt/Freeze Pt:=1495.C, #####F
Appearance and Odor:SILVER-GRAY METAL.

===== Stability and Reactivity Data =====

COBALT IS INCOMPATIBLE WITH ACETYLENE, HYDRAZINE, NITRATES AND
OXIDANTS.
Hazardous Decomposition Products:METAL PRODUCT
S THESELVES ARE NOT
REACTIVE, HOWEVER, CAUTION MUST BE TAKEN WHEN WELDING AND REMELTING
DUE TO FUMES AND GASES.

===== Toxicological Information =====

Toxicological Information:PHYSIOLOGICAL EFFECTS-COBALT CAUSES A
DERMATITIS OF THE ALLERGIC SENSITIVITY TYPE AT POINTS OF FRICTION.
COBALT TOXICITY ALSO RESULTS IN A PROGRESSIVE, DIFFUSE,
INTERSTITIAL PNEUMONIA WITH A NON-PRODUCTIVE COUGH, DYSPNEA ON
EXERTION, INTERSTITIAL FIBROSIS & CELL DAMAGE. OTHER WORKERS HAVE
EXPERIENCED A SENSITIZED RESPIRATORY DISEASE CHARACTERIZED BY
COUGH, WHEEZING AND SHORTNESS OF BREATH WHERE UPON REMOVAL FROM
ENVIRONMENT, THE SYMPTOMS SUBSIDE.

===== Other Information =====

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied,
warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.