NSN 2840-01-200-5337

Repairability:

Aircraft Gas Turbine Engine Oil Sump Housing - Page 1 of 1



| View Online at https://aerobasegroup.kr/nsn/2840-01-200-5337 |
|--|
| : |
| |
| |
| Shelf Life: |
| N/a |
| Unit Of Measure: |
| 1 ea |
| Demilitarization: |
| No |
| Fiig: |
| A530f0 |
| Hazmat: |
| No |

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.