NSN 2840-01-506-3542

Repairability:

Turbine Engine Cooling Plate - Page 1 of 1



ew Online at https://aerobasegroup.kr/nsn/2840-01-506-3542	
helf Life:	
⁄a	
nit Of Measure:	
ea	
emilitarization:	
es - demil/mli	
ig:	
23900	
azmat:	
0	

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.