NSN 3510-01-014-9106

Repairability:

Garment Finishing Tunnel - Page 1 of 1



If condemned or uneconomically repairable, then dispose at direct support (ds) level.