NSN 2840-01-281-3617

Repairability:

Aircraft Gas Turbine Engine Combustion Chamber - Page 1 of 1



View Online at https://aerobasegroup.kr/nsn/2840-01-281-3617	

Shelf Life:
N/a
Unit Of Measure:
1 ea
Demilitarization:
Yes - demil/mli
Fiig:
A530f0
Hazmat:
No

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.